



80087900008581472

CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	SERFAS FARMS LTD		
Address:	BOX 101		
City:	TURIN	Province:	AB
		Postal Code:	T0K2H0
Telephone Number:	(403) 715-7403		
Vehicle Identification Number:	2J91F4E34M1057281		
Make:	JBS	Model:	FT3860
Year:	2021	Unit Number:	ED27
Odometer:	KM	Licence Plate Number:	Z32622
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
C.R. Mechanics Ltd.	15785
Inspection Technician Name:	Technician Number:
Cam Reiter	B4953
Inspection Technician Signature:	
Inspection Date:	2026/08/25

2027/08/30

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered									
Trailer										kg									
Vehicle Information																			
VIN	2	J	9	1	F	4	E	3	4	M	1	0	5	7	2	8	1		
Unit Number			Year			Make			Model			Odometer							
ED27			2021			JBS			FT3860										
Registered Owner's Name															Plate Number				
SERFAS FARMS LTD															Z32622				
Address										Postal Code					Phone Number				
BOX 101										T0K2H0					(403) 715-7403				

Drum Brakes: A-Full Inspection with Drum Removed

Disc Brakes:

		LEFT	FRONT	RIGHT		
100 psi	100 psi	419.60 mm	Drums/Rotors	419.76 mm	100 psi	100 psi
10 mm	6 mm	21 mm	Linings/Pads	21 mm	7 mm	9 mm
		65 mm	Push Rod Travel	65 mm		
100 psi	100 psi	316.07 mm	Drums/Rotors	317.48 mm	100 psi	100 psi
12 mm	8 mm	21 mm	Linings/Pads	21 mm	10 mm	12 mm
		60 mm	Push Rod Travel	60 mm		
100 psi	100 psi	419.5 mm	Drums/Rotors	317.5 mm	100 psi	100 psi
11 mm	9 mm	21 mm	Linings/Pads	21 mm	7 mm	8 mm
		60 mm	Push Rod Travel	60 mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		

Park Brake Lining Left na mm Right na mm Trans na mm

Wheel Torque Checked ☒ Inner na ft lbs Outer 500 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓

NOTES:

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓		
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle			✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓		
2.4. Spring & Spring Attachment	✓						

NOTES:

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System			✓
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components			✓
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components			✓
3H.8. Vacuum System			✓	3H.19. Brake Performance			✓
3H.9. Air-Boosted Trailer Brake System			✓				

NOTES:

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System	✓		
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)	✓		
3A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components			✓
3A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)	✓		
3A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)			✓
3A.14. Brake Chamber	✓			3A.23. Brake Performance	✓		
3A.15. Drum Brake System Components	✓						

NOTES:

abs light on/last middle axle has leaking service fitting/replace fitting/replace abs sensor

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle			✓
4.4. Kingpin			✓				

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 5 - Instruments and Auxiliary Equipment								
Component	P	F	NA	Component	P	F	NA	
5.1. Fire Extinguisher			✓					

NOTES:

Section 6 - Lamps								
Component	P	F	NA	Component	P	F	NA	
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓			
6.2. Reflex Reflector	✓							

NOTES:

3way light in back doesnt work/repair wiring

Section 7 - Electrical System								
Component	P	F	NA	Component	P	F	NA	
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓			
7.2. Battery			✓					

NOTES:

Section 8 - Body								
Component	P	F	NA	Component	P	F	NA	
8.5. Cargo Body	✓			8.11. Refrigeration/Heater Unit Fuel System			✓	
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓			
8.7. Unitized Body Elements	✓			8.22. Landing Gear on Trailer	✓			
8.8. Cab or Cargo Door	✓			8.23. Sliding Axle Assembly (Sliding Bogie)				✓
8.9. Cargo Tank or Vessel	✓			8.24. Aerodynamic Device & Attachment				✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.25. Rear Impact Guard (RIG)				✓

NOTES:

middle axle inner axle seal leak/replace seal
last axle right tire has no tread/replace tire
has hole in box on passenger side /weld up side

Section 9 - Tires and Wheels								
Component	P	F	NA	Component	P	F	NA	
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓			
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim				✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System				✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System				✓
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓			
9.6. Wheel Bearing	✓							

NOTES:


Section 10 - Couplers and Hitches								
Component	P	F	NA	Component	P	F	NA	
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device				✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.7. Fifth Wheel Coupler				✓
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch	✓			10.8. Oscillating Fifth Wheel Coupler				✓
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer				✓
10.5. Roll-Coupling Hitch			✓					

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8581472) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2026/08/24	B4953	15785	

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2026/08/25

Customer Signature