



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	VOS TRANSPORT LTD		
Address:	PO BOX 445		
City:	GRANUM	Province:	AB
		Postal Code:	T0L1A0
Telephone Number:	(403) 330-3871		
Vehicle Identification Number:	1GRAA0629CB707591		
Make:	GREATDANE	Model:	HEATER
Year:	2012	Unit Number:	
Odometer:	KM	Licence Plate Number:	6JH010
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
A.S.A.P Truck & Trailer Repairs Ltd.	13437
Inspection Technician Name:	Technician Number:
Ryan Dobson	C7814
Inspection Technician Signature:	
Inspection Date:	2024/06/21

2025/06/30



COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Form containing vehicle information: Type of Vehicle (Trailer), Gross Vehicle Weight (kg), VIN (1GRAA0629CB707591), Unit Number, Year (2012), Make (GREATDANE), Model (HEATER), Odometer, Registered Owner's Name (VOS TRANSPORT LTD), Address (PO BOX 445), Postal Code (T0L1A0), Phone Number (403) 330-3871. Includes tables for Brakes (LEFT, FRONT, RIGHT) and Park Brake Linings.

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Form containing inspection sections: Section 1 - Power Train (1.2 Exhaust System), APPENDIX "A" (A.1 Liquefied Petroleum Gas, A.2 Compressed Natural Gas, A.3 Liquefied Natural Gas), Section 2 - Suspension (2.1 Suspension & Frame Attachments, 2.2 Axle Assembling & Tracking Components, 2.3 Axle & Axle Assembly, 2.4 Spring & Spring Attachment), Section 3H - Hydraulic Brakes (3H.1 Hydraulic System Components, 3H.6 Air-Over-Hydraulic Brake System, 3H.7 Surge Brake Controller, 3H.8 Vacuum System, 3H.9 Air-Bushed Trailer Brake System), Section 3A - Air Brakes (3A.3 Air System Leakage, 3A.4 Air Tank, 3A.8 Brake Valves & Controls, 3A.12 Parking Brake & Emergency Application, 3A.13 Air System Components, 3A.14 Brake Chamber, 3A.15 Drum Brake System Components, 3A.16 S-Cam Drum Brake System, 3A.17 Brake Shoe Travel (Wedge Brakes), 3A.18 Disc Brake System Components, 3A.20 AirLock Brake System (ABS), 3A.22 Stability Control System (FSC) or (RSS), 3A.23 Brake Performance), Section 4 - Steering (4.1 Steering Control & Linkage, 4.4 Kingpin). Includes notes: RIGHT FRONT SHOCK LEAKING - REPLACED; LEVELING VALVE LINKAGE WORN OUT - REPLACED; ALL CLEVIS PINS WORN - REPLACED WITH BOTH L-SIDE CLEVIS.

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Form containing inspection sections: Section 5 - Instruments and Auxiliary Equipment (5.1 Fuel Gauge/Shift), Section 6 - Lamps (6.1 Required Lamps, 6.2 Reflector), Section 7 - Electrical System (7.1 Wiring, 7.2 Battery), Section 8 - Body (8.5 Cargo Body, 8.6 Frame Rails & Mounts, 8.7 Untreated Body Elements, 8.8 Cab or Cargo Door, 8.9 Cargo Tank or Vessel, 8.10 Body Device or Equipment Attached to Mounted to the Vehicle, 8.11 Refrigeration Heater Unit Fuel System, 8.21 Fender Mud Flap, 8.22 Landing Gear on Trailer, 8.23 Sliding Axle Assembly (Sliding Brakes), 8.24 Aerodynamic Device & Attachment, 8.25 Rear Impact Guard (RIG)), Section 9 - Tires and Wheels (9.1 Tire Tread Depth, 9.2 Tire Tread Condition, 9.3 Tire Sidewall & Manufacturer Markings, 9.4 Tire Inflation Pressure, 9.5 Wheel Hub, 9.6 Wheel Bearings, 9.7 Wheel Rim, 9.8 Multi-Piece Wheel Rim, 9.9 Spoke Wheel/Dismountable Rim System, 9.10 Disc Wheel System, 9.11 Wheel Fasteners (Nuts, Bolts & Studs)), Section 10 - Couplers and Hitches (10.1 Hitch Assembly, Structure & Attaching Components, 10.2 Secondary Attachment (Safety Chain or Cable), 10.3 Pin-to-Hook Pin Hitch or Coupler Hitch, 10.4 Ball Type Hitch, 10.5 Roll-Coupling Hitch, 10.6 Automated Coupling Device, 10.7 Fifth Wheel Coupler, 10.8 Oscillating Fifth Wheel Coupler, 10.9 Ball-Bearing Type Turntable on Trailer).

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Form containing notes: PINTLE HITCH SEIZED - UNSEIZED. Certification section with Date of Inspection (2024/06/21), Technician Number (C7814), Facility Number (13437), and Customer Acknowledgment section with Date (2024/06/21) and Customer Signature.



Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is “sold as is” no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture