



80087500008196081

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate - Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Electric
Owner Name:	BLACK & MCDONALD LTD		
Address:	75 COMMERCE VALLEY DR E		
City:	MARKHAM	Province:	ON
		Postal Code:	L3T7N9
Telephone Number:	(403) 826-0736		
Vehicle Identification Number:	46UFU1636L1221646		
Make:	Roadclipper	Model:	LPT307
Year:	2020	Unit Number:	19805
Odometer:	KM	Licence Plate Number:	5WL143
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
DRB Mechanical Inc.	13000
Inspection Technician Name:	Technician Number:
Clayton Goddard	B0341
Inspection Technician Signature:	
Inspection Date:	2024/11/12

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered													
Trailer										kg													
Vehicle Information																							
VIN	4	6	U	F	U	1	6	3	6	L	1	2	2	1	6	4	6						
Unit Number 19805				Year 2020				Make Roadclipper				Model LPT307				Odometer							
Registered Owner's Name BLACK & MCDONALD LTD																Plate Number 5WL143							
Address 75 COMMERCE VALLEY DR E												Postal Code L3T7N9				Phone Number (403) 826-0736							

Drum Brakes: A-Full Inspection with Drum Removed

Disc Brakes:

		LEFT		FRONT		RIGHT			
80 psi	N/A psi	305.38 mm	Drums/Rotors	N/A mm		N/A psi	N/A psi	N/A mm	N/A mm
6 mm	N/A mm	5 mm	Linings/Pads	N/A mm					
		N/A mm	Push Rod Travel	N/A mm					
80 psi	N/A psi	305.46 mm	Drums/Rotors	305.30 mm		N/A psi	80 psi	N/A mm	6 mm
8 mm	N/A mm	5 mm	Linings/Pads	5 mm					
		N/A mm	Push Rod Travel	N/A mm					
80 psi	N/A psi	305.28 mm	Drums/Rotors	305.65 mm		N/A psi	80 psi	N/A mm	6 mm
1 mm	N/A mm	5 mm	Linings/Pads	5 mm					
		N/A mm	Push Rod Travel	N/A mm					
psi	psi	mm	Drums/Rotors	mm		psi	psi	mm	mm
mm	mm	mm	Linings/Pads	mm					
		mm	Push Rod Travel	mm					
psi	psi	mm	Drums/Rotors	mm		psi	psi	mm	mm
mm	mm	mm	Linings/Pads	mm					
		mm	Push Rod Travel	mm					
psi	psi	mm	Drums/Rotors	mm		psi	psi	mm	mm
mm	mm	mm	Linings/Pads	mm					
		mm	Push Rod Travel	mm					
Park Brake Lining Left N/A mm Right N/A mm Trans N/A mm									
Wheel Torque Checked ☒ Inner N/A ft lbs Outer 140 ft lbs									

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train						
Component	P	F	NA	Component	P	F NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*		✓

NOTES:

APPENDIX "A"						
Component	P	F	NA	Component	P	F NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System		✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓			

NOTES:

Section 2 - Suspension						
Component	P	F	NA	Component	P	F NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension		✓
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle		✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly		✓
2.4. Spring & Spring Attachment	✓					

NOTES:

REPLACED - AXLE 1 RIGHT STUB SHAFT BROKEN

Section 3H - Hydraulic Brakes						
Component	P	F	NA	Component	P	F NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System	✓	
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components	✓	
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components		✓
3H.8. Vacuum System			✓	3H.19. Brake Performance	✓	
3H.9. Air-Boosted Trailer Brake System			✓			

NOTES:

REPLACED - MISSING AXLE 1 RIGHT HUB/DRUM

Section 3A - Air Brakes						
Component	P	F	NA	Component	P	F NA
3A.3. Air System Leakage			✓	3A.16. S-Cam Drum Brake System		✓
3A.4. Air Tank			✓	3A.17. Brake Shoe Travel (Wedge Brakes)		✓
3A.8. Brake Valves & Controls			✓	3A.18. Disc Brake System Components		✓
3A.12. Parking Brake & Emergency Application			✓	3A.20. Anti-Lock Brake System (ABS)		✓
3A.13. Air System Components			✓	3A.22. Stability Control System (ESC) or (RSS)		✓
3A.14. Brake Chamber			✓	3A.23. Brake Performance		✓
3A.15. Drum Brake System Components			✓			

NOTES:

Section 4 - Steering						
Component	P	F	NA	Component	P	F NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle		✓
4.4. Kingpin			✓			

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

REPAIRED - CLUSTER OF 3 LIGHTS AT REAR NOT WORKING

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery	✓						

NOTES:

REPAIRED - BREAKAWAY SYSTEM NOT WORKING

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body	✓			8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements	✓			8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door	✓			8.23. Sliding Axle Assembly (Sliding Bogie)			✓
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.25. Rear Impact Guard (RIG)	✓		

NOTES:

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System			✓
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

REPLACED - MISSING AXLE 1 RIGHT HUB/DRUM
REPAIRED - AXLE 3 LEFT TIRE WORN OUT

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)	✓			10.7. Fifth Wheel Coupler			✓
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch	✓			10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				

358

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

NOTES:

REPLACED - SAFTEY CHAIN HOOKS

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8196081) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection

2024/11/12

Technician Number

B0341

Facility Number

13000

Signature

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2024/11/12

Customer Signature