

F03-7

Alberta Government

CV8637032



80087500008637032

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	DAYCHIEF TRACY THOMAS O/A CHIEF'S CONSTRUCTION		
Address:	PO BOX 1862		
City:	CARDSON	Province:	AB
		Postal Code:	T0K0K0
Telephone Number:	(403) 331-8013		
Vehicle Identification Number:	2D9CS3823J1012189		
Make:	Load Line	Model:	GCSSP-38
Year:	2018	Unit Number:	ATCD-130
Odometer:	KM	Licence Plate Number:	6EM210
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
A V Brake Ltd.	10727
Inspection Technician Name:	Technician Number:
Glenn Gauthier	B3242
Inspection Technician Signature:	<i>Glenn Gauthier</i>
Inspection Date:	2026/04/07

202 710 41 30



COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered									
Trailer										kg									
Vehicle Information																			
VIN	2	D	9	C	S	3	8	2	3	J	1	0	1	2	1	8	9		
Unit Number ATCD-130		Year 2018		Make Load Line				Model GCSSP-38				Odometer							
Registered Owner's Name DAYCHIEF TRACY THOMAS O/A CHIEF'S CONSTRUCTION																Plate Number 6EM210			
Address PO BOX 1862										Postal Code T0K0K0				Phone Number (403) 331-8013					

Drum Brakes: B-Wheel-on Full Inspection **Disc Brakes:**

		<u>LEFT</u>		<u>FRONT</u>		<u>RIGHT</u>			
88 psi 8 mm	93 psi 6 mm	420.77 mm	18 mm	420.38 mm	15 mm	420.38 mm	60 mm	93 psi 5 mm	92 psi 6 mm
93 psi 12 mm	0 psi 11 mm	420.62 mm	16 mm	420.58 mm	15 mm	420.58 mm	42 mm	94 psi 11 mm	91 psi 11 mm
87 psi 5 mm	92 psi 2 mm	421.14 mm	17 mm	420.98 mm	15 mm	420.98 mm	0 mm	95 psi 2 mm	91 psi 5 mm
_ psi _ mm	_ psi _ mm	_ mm	_ mm	_ mm	_ mm	_ mm	_ mm	_ psi _ mm	_ psi _ mm
_ psi _ mm	_ psi _ mm	_ mm	_ mm	_ mm	_ mm	_ mm	_ mm	_ psi _ mm	_ psi _ mm
_ psi _ mm	_ psi _ mm	_ mm	_ mm	_ mm	_ mm	_ mm	_ mm	_ psi _ mm	_ psi _ mm

Park Brake Lining Left NA mm Right NA mm Trans NA mm
 Wheel Torque Checked Inner NA ft lbs Outer 475 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train							
Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓

NOTES:

APPENDIX "A"							
Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

Section 2 - Suspension							
Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments				2.5. Air Suspension			
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle	✓		
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly			✓
2.4. Spring & Spring Attachment			✓				

NOTES:

2.7 LOOSE SHOCK (#3 AXLE)(bottom bolt replaced)

Section 3H - Hydraulic Brakes							
Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System			✓
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components			✓
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components			✓
3H.8. Vacuum System			✓	3H.19. Brake Performance			✓
3H.9. Air-Boosted Trailer Brake System			✓				

NOTES:

Section 3A - Air Brakes							
Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System	✓		
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓
3A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components			✓
3A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)	✓		
3A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)			✓
3A.14. Brake Chamber	✓			3A.23. Brake Performance			✓
3A.15. Drum Brake System Components	✓						

NOTES:

3A.3 AIR LINE LEAKING (#3 RH SPRING BRAKE)(repaired)
 3A.8 AIR LEAKING OUT OF SERVICE VALVE (OUT OF EXHAUST)(FRONT VALVE)
 3A.13 RUBBING AIR LINES (tied up)
 3A.14 BRAKE POT LEAKING OUT OF SERVICE SIDE (#3 RH #1 LH)(HOSE REMOVED FOR INSPECTION)(replaced)
 3A.14 BRAKE POT LOOSE OR NOT FULLY MOUNTED (#1 RH #2 RH)(replaced)
 3A.14 GAGE BOLT MISSING (#3 LH)(done)
 3A.16 SCAM WASHER HITTING DRUM (#3 RH)(removed drum & bent)

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 4 - Steering							
Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle			✓
4.4. Kingpin			✓				

NOTES:

Section 5 - Instruments and Auxiliary Equipment							
Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps							
Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

- 6.1 25% LED'S OUT (RH TAIL LIGHTS)(replaced)
- 6.1 ID LIGHT OUT (LH REAR)(repaired)
- 6.1 LIC PLATE LIGHT OUT (replaced)

Section 7 - Electrical System							
Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)			✓
7.2. Battery			✓				

NOTES:

Section 8 - Body							
Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body			✓	8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements	✓			8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door	✓			8.23. Sliding Axle Assembly (Sliding Bogie)			✓
8.9. Cargo Tank or Vessel	✓			8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.25. Rear Impact Guard (RIG)	✓		

NOTES:

- 8.6 CROSS BRACE BROKEN (IN FRONT OF #1 AXLE)(welded)
- 8.8 STOP NOT RETURNING FROM FULLY OPEN ON CLAM (RH)(freed up)

Section 9 - Tires and Wheels							
Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓		
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

- 9.4 TIRE PRESSURE SET TO 100 PSI (ALL BUT #2 LH OUTER)
- 9.4 TIRE OFF BEAD (#2 LH INNER)(repaired)

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY


Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.7. Fifth Wheel Coupler			✓
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.8. Oscillating Fifth Wheel Coupler	✓		
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED (Certificate #8637032)** the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.


Date of Inspection 2026/04/02	Technician Number B3242	Facility Number 10727	Signature 
---	-----------------------------------	---------------------------------	--

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2026/04/07

Customer Signature




Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is "sold as is" no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture