



CV8584193



80087800008584193

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	DOUBLE E TRANSPORT LTD.		
Address:	BOX 1870		
City:	ENCHANT	Province:	AB
		Postal Code:	TOKOV0
Telephone Number:	(306) 607-9424		
Vehicle Identification Number:	1FUJAHCG73LL09615		
Make:	Freightliner	Model:	Conventional
Year:	2003	Unit Number:	T002
Odometer:	166370 KM	Licence Plate Number:	
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Precision Heavy Truck Repair Ltd	Facility Number:	18574
Inspection Technician Name:	David Pike	Technician Number:	B8287
Inspection Technician Signature:			
Inspection Date:	2025/10/29		

2026/10/29



COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle **Truck** Gross Vehicle Weight registered **kg**

Vehicle Information
VIN 1 F U J A H C G 7 3 L L 0 9 6 1 5

Unit Number T002	Year 2003	Make Freightliner	Model Conventional	Odometer 166,370
Registered Owner's Name DOUBLE E TRANSPORT LTD.				Plate Number
Address BOX 1870		Postal Code T0K0V0		Phone Number (306) 607-9424

Drum Brakes: **A-Full Inspection with Drum Removed** Disc Brakes:

		LEFT		FRONT		RIGHT			
100 psi		382.60 mm	Drums/Rotors	382.25 mm				100 psi	
5 mm		7 mm	Linings/Pads	7 mm				7 mm	
		35 mm	Push Rod Travel	32 mm					
100 psi	100 psi	420.30 mm	Drums/Rotors	420.91 mm				100 psi	100 psi
14 mm	14 mm	16 mm	Linings/Pads	14 mm				9 mm	9 mm
		37 mm	Push Rod Travel	41 mm					
100 psi	100 psi	420.56 mm	Drums/Rotors	420.80 mm				100 psi	100 psi
13 mm	13 mm	19 mm	Linings/Pads	19 mm				15 mm	15 mm
		45 mm	Push Rod Travel	45 mm					
psi	psi	mm	Drums/Rotors	mm				psi	psi
mm	mm	mm	Linings/Pads	mm				mm	mm
		mm	Push Rod Travel	mm					
psi	psi	mm	Drums/Rotors	mm				psi	psi
mm	mm	mm	Linings/Pads	mm				mm	mm
		mm	Push Rod Travel	mm					
psi	psi	mm	Drums/Rotors	mm				psi	psi
mm	mm	mm	Linings/Pads	mm				mm	mm
		mm	Push Rod Travel	mm					

Park Brake Lining Left **NA** mm Right **NA** mm Trans **NA** mm

Wheel Torque Checked Inner **NA** ft lbs Outer **500** ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 8 - Body							
Component	P	F	NA	Component	P	F	NA
Vehicle							
8.11. Refrigeration/Heater Unit Fuel System (Reefer or Auxiliary Power Unit (APU))			✓	8.24. Aerodynamic Device & Attachment			✓

NOTES:

Section 9 - Tires and Wheels							
Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim (Applies to all wheel types)	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓		
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts and Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

Section 10 - Couplers and Hitches							
Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.5. Roll-Coupling Hitch			✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.6. Automated Coupling Device			✓
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.7. Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.8. Oscillating Fifth Wheel Coupler	✓		

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED (Certificate #8584193)** the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2025/10/28	B8287	18574	

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2025/10/29

Customer Signature



Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is "sold as is" no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture