



Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	624889 BC O/A EVANS TRUCKING LTD		
Address:	#200-135 10 AVE S		
City:	CRANBROOK	Province:	BC
		Postal Code:	V1C2N1
Telephone Number:	(403) 345-3558		
Vehicle Identification Number:	2LDPF4825GL062328		
Make:	LODE KING	Model:	FLAT DECK
Year:	2016	Unit Number:	T-450
Odometer:	KM	Licence Plate Number:	92708J
		Province:	BC

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Evans HD Ltd.	19136
Inspection Technician Name:	Technician Number:
Calvin Olfert	C3142
Inspection Technician Signature:	
Inspection Date:	2026/09/21

2027/09/30



Type of Vehicle										Gross Vehicle Weight registered									
Trailer										kg									
Vehicle Information																			
VIN	2	L	D	P	F	4	8	2	5	G	L	0	6	2	3	2	8		
Unit Number T-450			Year 2016			Make LODE KING				Model FLAT DECK				Odometer					
Registered Owner's Name 624889 BC O/A EVANS TRUCKING LTD															Plate Number 92708J				
Address #200-135 10 AVE S										Postal Code V1C2N1					Phone Number (403) 345-3558				

		LEFT	FRONT	RIGHT		
<u>100</u> psi	<u>100</u> psi	<u>N/A</u> in	Drums/Rotors	<u>N/A</u> in	<u>100</u> psi	<u>100</u> psi
<u>11/32</u> in	<u>8/32</u> in	<u>5/8</u> in	Linings/Pads	<u>5/8</u> in	<u>13/32</u> in	<u>13/32</u> in
		<u>1.25</u> in	Push Rod Travel	<u>1.25</u> in		
<u>100</u> psi	<u>100</u> psi	<u>N/A</u> in	Drums/Rotors	<u>N/A</u> in	<u>100</u> psi	<u>100</u> psi
<u>13/32</u> in	<u>12/32</u> in	<u>11/16</u> in	Linings/Pads	<u>9/16</u> in	<u>11/32</u> in	<u>11/32</u> in
		<u>1.25</u> in	Push Rod Travel	<u>1.25</u> in		
<u> </u> psi	<u> </u> psi	<u> </u> in	Drums/Rotors	<u> </u> in	<u> </u> psi	<u> </u> psi
<u> </u> in	<u> </u> in	<u> </u> in	Linings/Pads	<u> </u> in	<u> </u> in	<u> </u> in
		<u> </u> in	Push Rod Travel	<u> </u> in		
<u> </u> psi	<u> </u> psi	<u> </u> in	Drums/Rotors	<u> </u> in	<u> </u> psi	<u> </u> psi
<u> </u> in	<u> </u> in	<u> </u> in	Linings/Pads	<u> </u> in	<u> </u> in	<u> </u> in
		<u> </u> in	Push Rod Travel	<u> </u> in		
<u> </u> psi	<u> </u> psi	<u> </u> in	Drums/Rotors	<u> </u> in	<u> </u> psi	<u> </u> psi
<u> </u> in	<u> </u> in	<u> </u> in	Linings/Pads	<u> </u> in	<u> </u> in	<u> </u> in
		<u> </u> in	Push Rod Travel	<u> </u> in		
<u> </u> psi	<u> </u> psi	<u> </u> in	Drums/Rotors	<u> </u> in	<u> </u> psi	<u> </u> psi
<u> </u> in	<u> </u> in	<u> </u> in	Linings/Pads	<u> </u> in	<u> </u> in	<u> </u> in
		<u> </u> in	Push Rod Travel	<u> </u> in		
Park Brake Lining Left <u>N/A</u> in Right <u>N/A</u> in Trans <u>N/A</u> in Wheel Torque Checked ☒ Inner <u>N/A</u> ft lbs Outer <u>500</u> ft lbs						

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train						
Component	P	F	NA	Component	P	F NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*		✓

NOTES:

APPENDIX "A"						
Component	P	F	NA	Component	P	F NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System		✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓			

NOTES:

Section 2 - Suspension						
Component	P	F	NA	Component	P	F NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓	
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle		✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓	
2.4. Spring & Spring Attachment			✓			

NOTES:

Both shocks on #1 axle and P/S shock on #2 axle leaking

Replaced all 3 shocks.

Section 3H - Hydraulic Brakes						
Component	P	F	NA	Component	P	F NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System		✓
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components		✓
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components		✓
3H.8. Vacuum System			✓	3H.19. Brake Performance		✓
3H.9. Air-Boosted Trailer Brake System			✓			

NOTES:

Section 3A - Air Brakes						
Component	P	F	NA	Component	P	F NA
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System	✓	
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)		✓
3A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components		✓
3A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)	✓	
3A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)		✓
3A.14. Brake Chamber	✓			3A.23. Brake Performance	✓	
3A.15. Drum Brake System Components	✓					

NOTES:

Wheels on limited, Haldex pins and bushings worn/loose

Set all brakes, replaced all haldex pins and bushings.

Section 4 - Steering						
Component	P	F	NA	Component	P	F NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle		✓
4.4. Kingpin			✓			

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

NOTES:

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking			✓
6.2. Reflex Reflector	✓						

NOTES:

Multiple marker lights out on the D/S near the front.

Repaired lights as required.

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)			✓
7.2. Battery			✓				

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body	✓			8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements	✓			8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door			✓	8.23. Sliding Axle Assembly (Sliding Bogie)	✓		
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.25. Rear Impact Guard (RIG)	✓		

NOTES:

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System			✓
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

Set all tire pressures to 100psi

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.7. Fifth Wheel Coupler	✓		

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8781538) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2026/09/18	C3142	19136	

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2026/09/21

Customer Signature



Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is "sold as is" no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture