



CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	624889 BC O/A EVANS TRUCKING LTD		
Address:	#200-135 10 AVE S		
City:	CRANBROOK	Province:	BC
Postal Code:	V1C2N1		
Telephone Number:	(403) 345-3558		
Vehicle Identification Number:	3AKJGLDR5HSJB2709		
Make:	Freightliner	Model:	Cascadia
Year:	2017	Unit Number:	04
Odometer:	1417540 KM	Licence Plate Number:	69261P
Province:	BC		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Evans HD Ltd.	19136
Inspection Technician Name:	Technician Number:
Calvin Olfert	C3142
Inspection Technician Signature:	
Inspection Date:	2026/06/22

2027/06/30

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRUCK AND TRUCK-TRACTOR**

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered											
Truck										kg											
Vehicle Information																					
VIN	3	A	K	J	G	L	D	R	5	H	S	J	B	2	7	0	9				
Unit Number 04			Year 2017			Make Freightliner			Model Cascadia			Odometer 1,417,540									
Registered Owner's Name 624889 BC O/A EVANS TRUCKING LTD														Plate Number 69261P							
Address #200-135 10 AVE S										Postal Code V1C2N1				Phone Number (403) 345-3558							

Drum Brakes: A-Full Inspection with Drum Removed

Disc Brakes:

		LEFT	FRONT	RIGHT		
100 psi	16/32 in	16.590 in	Drums/Rotors	16.595 in	100 psi	16/32 in
		11/16 in	Linings/Pads	5/8 in		
		1 3/4 in	Push Rod Travel	1 3/4 in		
N/A psi	110 psi	16.500 in	Drums/Rotors	16.500 in	110 psi	N/A psi
N/A in	14/32 in	13/16 in	Linings/Pads	13/16 in	14/32 in	N/A in
		1 1/2 in	Push Rod Travel	1 1/2 in		
N/A psi	110 psi	16.500 in	Drums/Rotors	16.500 in	110 psi	N/A psi
N/A in	19/32 in	13/16 in	Linings/Pads	13/16 in	20/32 in	N/A in
		1 1/2 in	Push Rod Travel	1 1/2 in		
psi	psi	in	Drums/Rotors	in	psi	psi
in	in	in	Linings/Pads	in	in	in
		in	Push Rod Travel	in		
psi	psi	in	Drums/Rotors	in	psi	psi
in	in	in	Linings/Pads	in	in	in
		in	Push Rod Travel	in		
psi	psi	in	Drums/Rotors	in	psi	psi
in	in	in	Linings/Pads	in	in	in
		in	Push Rod Travel	in		
Park Brake Lining Left <u>N/A</u> in Right <u>N/A</u> in Trans <u>N/A</u> in Wheel Torque Checked ☒ Inner <u>N/A</u> ft lbs Outer <u>500</u> ft lbs						

8.10. Body, Device or Equipment Attached or Mounted to the	☒	8.20. Seat Belt/Occupant Restraint	☒
	☒	8.21. Fender/Mud Flap	☒

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 8 - Body						
Component	P	F	NA	Component	P	F NA
Vehicle						
8.11. Refrigeration/Heater Unit Fuel System (Reefer or Auxiliary Power Unit (APU))			✓	8.24. Aerodynamic Device & Attachment		✓

NOTES:
8.3 Replaced cab air bags. 8.13 replaced P/S windshield. 8.18 Replaced D/S mirror with good used mirror.

Section 9 - Tires and Wheels						
Component	P	F	NA	Component	P	F NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim (Applies to all wheel types)	✓	
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim		✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System		✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓	
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts and Studs)	✓	
9.6. Wheel Bearing	✓					

NOTES:
9.4 Adjusted drives to 110 psi.

Section 10 - Couplers and Hitches						
Component	P	F	NA	Component	P	F NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.5. Roll-Coupling Hitch		✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.6. Automated Coupling Device		✓
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.7. Fifth Wheel Coupler	✓	
10.4. Ball Type Hitch			✓	10.8. Oscillating Fifth Wheel Coupler		✓

NOTES:
10.7 Replaced 5th wheel pins & bushings.

Certification			
The Vehicle for which this Record of Inspection is issued has PASSED (Certificate #8672597) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.			
Date of Inspection 2026/06/16	Technician Number C3142	Facility Number 19136	Signature

Customer Acknowledgment	
I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.	Date (Year/Month/Day) 2026/06/22 Customer Signature



Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is “sold as is” no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture