

L01-23



CV8532026



80087300008532026

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Cruz Lite Farm Ltd		
Address:	PO Box 654 Stn Main		
City:	Brooks	Province:	AB
		Postal Code:	T1R1B6
Telephone Number:	(403) 362-8686		
Vehicle Identification Number:	2MFB2R5D3KR009152		
Make:	Midland	Model:	SL3000 End Dump
Year:	2019	Unit Number:	79
Odometer:	KM	Licence Plate Number:	6AU510
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Cruz Lite Trucking LTD	19226
Inspection Technician Name:	Technician Number:
Craig Charlton	C7731
Inspection Technician Signature:	
Inspection Date:	2025/08/16

2026/08/16



COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered											
Trailer										kg											
Vehicle Information																					
VIN	2	M	F	B	2	R	5	D	3	K	R	0	0	9	1	5	2				
Unit Number				Year				Make				Model				Odometer					
79				2019				Midland				SL3000 End Dump									
Registered Owner's Name																Plate Number					
Cruz Lite Farm Ltd																6AU510					
Address												Postal Code				Phone Number					
PO Box 654 Stn Main												T1R1B6				(403) 362-8686					

Drum Brakes: **B-Wheel-on Full Inspection**

Disc Brakes:

		LEFT	FRONT	RIGHT		
100 psi	100 psi	NA mm	Drums/Rotors	NA mm	100 psi	100 psi
6 mm	6 mm	18 mm	Linings/Pads	18 mm	8 mm	8 mm
		43 mm	Push Rod Travel	43 mm		
100 psi	100 psi	NA mm	Drums/Rotors	NA mm	100 psi	100 psi
8 mm	8 mm	19 mm	Linings/Pads	18 mm	7 mm	7 mm
		43 mm	Push Rod Travel	43 mm		
100 psi	100 psi	NA mm	Drums/Rotors	NA mm	100 psi	100 psi
10 mm	10 mm	18 mm	Linings/Pads	18 mm	10 mm	10 mm
		43 mm	Push Rod Travel	43 mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		

Park Brake Lining Left 18 mm Right 18 mm Trans NA mm


Wheel Torque Checked Inner 500 ft lbs Outer 500 ft lbs

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8532026) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2025/08/16	C7731	19226	

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2025/08/16

Customer Signature



Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is "sold as is" no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture