



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate  
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Cruz Lite Trucking Ltd		
Address:	PO Box 654 Stn Main		
City:	Brooks	Province:	AB
		Postal Code:	T1R1B6
Telephone Number:	(403) 362-8686		
Vehicle Identification Number:	2MFB2R5D3MR009610		
Make:	Midland	Model:	Dump
Year:	2021	Unit Number:	25
Odometer:	KM	Licence Plate Number:	6GS845
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Cruz Lite Trucking LTD	Facility Number:	19226
Inspection Technician Name:	Craig Charlton	Technician Number:	C7731
Inspection Technician Signature:			
Inspection Date:	2025/09/20		

2026/09/20





## COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

<b>Type of Vehicle</b>										<b>Gross Vehicle Weight registered</b>											
Trailer										kg											
<b>Vehicle Information</b>																					
VIN	2	M	F	B	2	R	5	D	3	M	R	0	0	9	6	1	0				
Unit Number 25			Year 2021			Make Midland			Model Dump			Odometer									
Registered Owner's Name Cruz Lite Trucking Ltd															Plate Number 6GS845						
Address PO Box 654 Stn Main										Postal Code T1R1B6					Phone Number (403) 362-8686						

Drum Brakes: **A-Full Inspection with Drum Removed**

Disc Brakes:

		LEFT	FRONT	RIGHT		
100 psi	100 psi	420.55 mm	Drums/Rotors	420.43 mm	100 psi	100 psi
10 mm	10 mm	16 mm	Linings/Pads	15 mm	10 mm	10 mm
		43 mm	Push Rod Travel	43 mm		
100 psi	100 psi	419.60 mm	Drums/Rotors	420.84 mm	100 psi	100 psi
10 mm	10 mm	22 mm	Linings/Pads	14 mm	10 mm	10 mm
		43 mm	Push Rod Travel	43 mm		
100 psi	100 psi	419.87 mm	Drums/Rotors	420.01 mm	100 psi	100 psi
9 mm	11 mm	22 mm	Linings/Pads	22 mm	10 mm	11 mm
		43 mm	Push Rod Travel	43 mm		
__ psi	__ psi	__ mm	Drums/Rotors	__ mm	__ psi	__ psi
__ mm	__ mm	__ mm	Linings/Pads	__ mm	__ mm	__ mm
		__ mm	Push Rod Travel	__ mm		
__ psi	__ psi	__ mm	Drums/Rotors	__ mm	__ psi	__ psi
__ mm	__ mm	__ mm	Linings/Pads	__ mm	__ mm	__ mm
		__ mm	Push Rod Travel	__ mm		
__ psi	__ psi	__ mm	Drums/Rotors	__ mm	__ psi	__ psi
__ mm	__ mm	__ mm	Linings/Pads	__ mm	__ mm	__ mm
		__ mm	Push Rod Travel	__ mm		

Park Brake Lining Left 16 mm Right 14 mm Trans NA mm

Wheel Torque Checked  Inner 500 ft lbs Outer 500 ft lbs

**COMMERCIAL VEHICLE RECORD OF INSPECTION  
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

**NOTES:**

**Certification**

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8532037) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2025/09/20	C7731	19226	

**Customer Acknowledgment**

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.	Date (Year/Month/Day) 2025/09/20
	Customer Signature



## Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is "sold as is" no warranties made or implied

---

Brennan LeBlanc  
Divisional Operations Manager  
Western Canada Agriculture