



CV8634226



80087600008634226

CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

| | | | |
|--------------------------------|------------------------|-----------------------|----------|
| Vehicle Type: | Trailer | Seating Capacity: | |
| GVW: | kg | Brake Type: | Air |
| Owner Name: | Cruz Lite Trucking Ltd | | |
| Address: | PO Box 654 Stn Main | | |
| City: | Brooks | Province: | AB |
| | | Postal Code: | T1R1B6 |
| Telephone Number: | (403) 362-8686 | | |
| Vehicle Identification Number: | 2MFB2R5D3TR011372 | | |
| Make: | Midland | Model: | Slx3 End |
| Year: | 2026 | Unit Number: | 47 |
| Odometer: | KM | Licence Plate Number: | 6XC175 |
| | | Province: | AB |

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

| | | | |
|----------------------------------|------------------------|--------------------|-------|
| Inspection Facility Name: | Cruz Lite Trucking LTD | Facility Number: | 19226 |
| Inspection Technician Name: | Craig Charlton | Technician Number: | C7731 |
| Inspection Technician Signature: | | | |
| Inspection Date: | 2026/04/22 | | |

2026/04/22



COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

| | | | | | | | | | | | | | | | | | | | | | | | | |
|--|---|---|---|---|---------------------|---|---|---|---|--|---|---|---|---|---------------------------------------|---|---|--|--|-----------------|--|--|--|--|
| Type of Vehicle | | | | | | | | | | Gross Vehicle Weight registered | | | | | | | | | | | | | | |
| Trailer | | | | | | | | | | kg | | | | | | | | | | | | | | |
| Vehicle Information | | | | | | | | | | | | | | | | | | | | | | | | |
| VIN | 2 | M | F | B | 2 | R | 5 | D | 3 | T | R | 0 | 1 | 1 | 3 | 7 | 2 | | | | | | | |
| Unit Number 47 | | | | | Year 2026 | | | | | Make Midland | | | | | Model Six3 End | | | | | Odometer | | | | |
| Registered Owner's Name Cruz Lite Trucking Ltd | | | | | | | | | | | | | | | Plate Number 6XC175 | | | | | | | | | |
| Address PO Box 654 Stn Main | | | | | | | | | | Postal Code T1R1B6 | | | | | Phone Number (403) 362-8686 | | | | | | | | | |

Drum Brakes: B-Wheel-on Full Inspection

Disc Brakes:

| | | LEFT | FRONT | RIGHT | | |
|---------|---------|-------|-----------------|-------|---------|---------|
| 100 psi | 100 psi | NA mm | Drums/Rotors | NA mm | 100 psi | 100 psi |
| 10 mm | 10 mm | 19 mm | Linings/Pads | 20 mm | 10 mm | 10 mm |
| | | 43 mm | Push Rod Travel | 43 mm | | |
| 100 psi | 100 psi | NA mm | Drums/Rotors | NA mm | 100 psi | 100 psi |
| 13 mm | 14 mm | 20 mm | Linings/Pads | 20 mm | 14 mm | 14 mm |
| | | 43 mm | Push Rod Travel | 43 mm | | |
| 100 psi | 100 psi | NA mm | Drums/Rotors | NA mm | 100 psi | 100 psi |
| 7 mm | 7 mm | 19 mm | Linings/Pads | 19 mm | 6 mm | 6 mm |
| | | 43 mm | Push Rod Travel | 43 mm | | |
| __ psi | __ psi | __ mm | Drums/Rotors | __ mm | __ psi | __ psi |
| __ mm | __ mm | __ mm | Linings/Pads | __ mm | __ mm | __ mm |
| | | __ mm | Push Rod Travel | __ mm | | |
| __ psi | __ psi | __ mm | Drums/Rotors | __ mm | __ psi | __ psi |
| __ mm | __ mm | __ mm | Linings/Pads | __ mm | __ mm | __ mm |
| | | __ mm | Push Rod Travel | __ mm | | |
| __ psi | __ psi | __ mm | Drums/Rotors | __ mm | __ psi | __ psi |
| __ mm | __ mm | __ mm | Linings/Pads | __ mm | __ mm | __ mm |
| | | __ mm | Push Rod Travel | __ mm | | |

Park Brake Lining Left 19 mm Right 19 mm Trans NA mm

Wheel Torque Checked Inner 500 ft lbs Outer 500 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8634226) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

| | | | |
|---|-----------------------------------|---------------------------------|--|
| Date of Inspection 2026/04/22 | Technician Number C7731 | Facility Number 19226 | Signature  |
|---|-----------------------------------|---------------------------------|--|

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2026/04/22

Customer Signature



Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is “sold as is” no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture