

L04-1



CV8317365



80087600008317365

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	24500 kg	Brake Type:	Air
Owner Name:	HADNHILLS FARMING CO		
Address:	RR 3		
City:	HANNA	Province:	AB
		Postal Code:	T0J 1P0
Telephone Number:	(403) 854-4323		
Vehicle Identification Number:	2FZXKMCBXYAB34064		
Make:	Sterling	Model:	Sterling
Year:	2000	Unit Number:	104
Odometer:	399374 KM	Licence Plate Number:	CCT6265
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Glover International Trucks Ltd.	13266
Inspection Technician Name:	Technician Number:
Brady Bagley	D1540
Inspection Technician Signature:	
Inspection Date:	2026/04/28

202 7104130



COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle Truck										Gross Vehicle Weight registered 24500 kg									
Vehicle Information																			
VIN		2	F	Z	X	K	M	C	B	X	Y	A	B	3	4	0	6	4	
Unit Number 104				Year 2000				Make Sterling				Model Sterling				Odometer 399,374			
Registered Owner's Name HADNHILLS FARMING CO															Plate Number CCT6265				
Address RR 3										Postal Code T0J 1P0					Phone Number (403) 854-4323				

Drum Brakes: **A-Full inspection with Drum Removed** Disc Brakes:

		<u>LEFT</u>		<u>FRONT</u>		<u>RIGHT</u>			
100 psi	5 mm	420.36 mm	15 mm	Drums/Rotors	420.40 mm	16 mm	38 mm	100 psi	6 mm
				Linings/Pads					
				Push Rod Travel					
100 psi	13 mm	420.60 mm	15 mm	Drums/Rotors	420.90 mm	16 mm	40 mm	100 psi	7 mm
100 psi	15 mm			Linings/Pads				100 psi	2 mm
				Push Rod Travel					
100 psi	10 mm	419.10 mm	13 mm	Drums/Rotors	419.10 mm	13 mm	40 mm	100 psi	9 mm
100 psi	10 mm			Linings/Pads				100 psi	13 mm
				Push Rod Travel					
psi	mm	mm	mm	Drums/Rotors	mm	mm	mm	psi	mm
				Linings/Pads					
				Push Rod Travel					
psi	mm	mm	mm	Drums/Rotors	mm	mm	mm	psi	mm
				Linings/Pads					
				Push Rod Travel					
psi	mm	mm	mm	Drums/Rotors	mm	mm	mm	psi	mm
				Linings/Pads					
				Push Rod Travel					

Park Brake Lining Left NA mm Right NA mm Trans NA mm
 Wheel Torque Checked Inner NA ft lbs Outer 475 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.11. Parking Brake & Emergency Application	✓						

NOTES:

REPLACED BOTH AXLE # 2 SLACKS & BRAKE POTS, REPLACED BOTH AXLE # 3 DRUMS

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control and Linkage	✓			4.4. Kingpin	✓		
4.2. Power Steering System (Hydraulic and Electric)	✓			4.5. Self-Steer and Controlled-Steer Axle			✓
4.3. Steering Operation (Active Steer Axle)	✓						

NOTES:

REPLACED AXLE # 1 RH DRAG LINK

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher	✓			5.8. Heater & Windshield Defroster	✓		
5.2. Hazard Warning Kit	✓			5.9. Fuel-Burning Auxiliary Heater			✓
5.3. Horn	✓			5.10. Chain/"Headache" Rack	✓		
5.5. Speedometer	✓			5.11. Auxiliary Controls and Devices	✓		
5.6. Odometer	✓			5.12. Auxiliary Drive Controls	✓		
5.7. Windshield Wiper/Washer	✓						

NOTES:

REPAIRED WASHER SYSTEM

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.4. Instrument Panel Lamps	✓		
6.2. Reflex Reflector	✓			6.5. Headlamp Aim	✓		
6.3. Retro-Reflective Marking	✓						

NOTES:

REPLACED LH HEADLAMPS, REPAIRED REAR LIGHTS, REPAIRED LICENSE PLATE LIGHT

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)			✓
7.2. Battery	✓						

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.1. Hood or Engine Enclosure	✓			8.12. Bumper	✓		
8.2. Tilt Cab			✓	8.13. Windshield	✓		
8.3. Air-Suspended Cab			✓	8.14. Side Windows	✓		
8.4. Cab and Passenger-Vehicle Body	✓			8.15. Rear Window	✓		
8.5. Cargo Body	✓			8.16. Interior Sun Visor	✓		
8.6. Frame, Rails & Mounts	✓			8.17. Exterior Windshield Sun Visor	✓		
8.7. Unitized Body Elements	✓			8.18. Rear-View Mirror	✓		
8.8. Cab or Cargo Door	✓			8.19. Seat	✓		
8.9. Cargo Tank or Vessel			✓	8.20. Seat Belt/Occupant Restraint	✓		
8.10. Body, Device or Equipment Attached or Mounted to the	✓			8.21. Fender/Mud Flap	✓		



Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is "sold as is" no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture