



CV8706801



80087900008706801

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	46500 kg	Brake Type:	Air
Owner Name:	GRIFFIN LOGISTICS LTD		
Address:	240019 FRONTIER PLACE SE		
City:	ROCKY VIEW	Province:	AB
		Postal Code:	T1X0N2
Telephone Number:	(306) 313-8666		
Vehicle Identification Number:	4V4NC9EJ2DN132743		
Make:	Volvo	Model:	VN
Year:	2013	Unit Number:	319
Odometer:	2537738 KM	Licence Plate Number:	0FW601
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Modern Truck and Trailer Repair Ltd.	20270
Inspection Technician Name:	Technician Number:
Ninderpal Sandhu	C8385
Inspection Technician Signature:	<i>Ninderpal Sandhu</i>
Inspection Date:	2026/05/29

2024/05/29



COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered									
Truck										46500 kg									
Vehicle Information																			
VIN	4	V	4	N	C	9	E	J	2	D	N	1	3	2	7	4	3		
Unit Number 319				Year 2013				Make Volvo				Model VN				Odometer 2,537,738			
Registered Owner's Name GRIFFIN LOGISTICS LTD																Plate Number 0FW601			
Address 240019 FRONTIER PLACE SE												Postal Code T1X0N2				Phone Number (306) 313-8666			

Drum Brakes: A-Full Inspection with Drum Removed

Disc Brakes:

		LEFT	FRONT	RIGHT		
100 psi	13 mm	420.48 mm	Drums/Rotors	419.65 mm	100 psi	13 mm
		16 mm	Linings/Pads	21 mm		
		37 mm	Push Rod Travel	37 mm		
100 psi	8 mm	420.80 mm	Drums/Rotors	420.54 mm	100 psi	100 psi
		15 mm	Linings/Pads	14 mm		
		39 mm	Push Rod Travel	39 mm		
100 psi	14 mm	419.65 mm	Drums/Rotors	419.65 mm	100 psi	100 psi
		21 mm	Linings/Pads	21 mm		
		39 mm	Push Rod Travel	39 mm		
psi	mm	mm	Drums/Rotors	mm	psi	mm
		mm	Linings/Pads	mm		
		mm	Push Rod Travel	mm		
psi	mm	mm	Drums/Rotors	mm	psi	mm
		mm	Linings/Pads	mm		
		mm	Push Rod Travel	mm		
psi	mm	mm	Drums/Rotors	mm	psi	mm
		mm	Linings/Pads	mm		
		mm	Push Rod Travel	mm		
Park Brake Lining Left <u>N/A</u> mm Right <u>N/A</u> mm Trans <u>N/A</u> mm Wheel Torque Checked ☒ Inner <u>N/A</u> ft lbs Outer <u>500</u> ft lbs						

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 1 - Power Train								
Component	P	F	NA	Component	P	F	NA	
1.1. Accelerator Pedal/Throttle Actuator	✓			1.8. Engine Start Safety Feature	✓			
1.2. Exhaust System	✓			1.9. Gear Position Indicator	✓			
1.3. Emission Control Systems and Devices	✓			1.10. Engine or Accessory Drive Belt	✓			
1.4. Drive Shaft	✓			1.11. Hybrid Electric Vehicle & Electric Vehicle Power Train System			✓	
1.5. Clutch and Clutch Pedal	✓			1.12. Gasoline or Diesel Fuel System	✓			
1.6. Engine/Transmission Mount	✓			1.13. Pressurized or Liquefied Fuel System (LPG, CNG, & LNG)			✓	
1.7. Engine/Shut Down	✓			* SEE APPENDIX A*				

NOTES:

APPENDIX "A"								
Component	P	F	NA	Component	P	F	NA	
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓	
A.2. Compressed Natural Gas (CNG) Fuel System			✓					

NOTES:

Section 2 - Suspension								
Component	P	F	NA	Component	P	F	NA	
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓			
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer and Controlled-Steer Axle	✓			
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓			
2.4. Spring & Spring Attachment	✓							

NOTES:

REPAIRS COMPLETED A2 AND A3 TORQUE ROD BUSHING WORN OUT, TORQUE ROD REPLACED
REPAIRS COMPLETED A2 B/S AND A3 B/S SHOCK ABSORBER NEED TO REPLACE, REPLACED

Section 3H - Hydraulic Brakes								
Component	P	F	NA	Component	P	F	NA	
3H.1. Hydraulic System Components			✓	3H.13. Disc Brake System Components			✓	
3H.2. Brake Pedal/Actuator			✓	3H.14. Mechanical Parking Brake			✓	
3H.3. Vacuum Assist (Boost) System			✓	3H.15. Spring-Applied Air-Released Parking Brake			✓	
3H.4. Hydraulic Assist (Boost) System			✓	3H.16. Spring-Applied Hydraulic-Released Parking Brake			✓	
3H.5. Air Assist (Boost) System			✓	3H.17. Anti-Lock Brake System (ABS)			✓	
3H.6. Air-Over-Hydraulic Brake System			✓	3H.18. Stability Control System			✓	
3H.11. Brake System Indicator Lamps			✓	3H.19. Brake Performance			✓	
3H.12. Drum Brake System Components			✓					

NOTES:

Section 3A - Air Brakes								
Component	P	F	NA	Component	P	F	NA	
3A.1. Air Compressor	✓			3A.13. Air System Components	✓			
3A.2. Air Supply System	✓			3A.14. Brake Chamber	✓			
3A.4. Air Tank	✓			3A.15. Drum Brake System Components	✓			
3A.5. Air Tank Check Valves	✓			3A.16. S-Cam Drum Brake System	✓			
3A.6. Brake Pedal/Actuator	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓	
3A.7. Treadle Valve and Trailer Hand Valve	✓			3A.18. Disc Brake System Components			✓	
3A.8. Brake Valves & Controls	✓			3A.19. Anti-Lock Brake System (ABS)	✓			
3A.9. Proportioning, Inversion or Modulation Valve	✓			3A.21. Stability Control System	✓			
3A.10. Towing Vehicle (Tractor) Protection System	✓			3A.23. Brake Performance	✓			

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 3A - Air Brakes						
Component	P	F	NA	Component	P	F NA
3A.11. Parking Brake & Emergency Application	☒					

NOTES:

REPAIRS COMPLETED A1 R/S AND A3 B/S BRAKE SHOE BROKEN, REPLACED

REPAIRS COMPLETED A1 R/S AND A3 B/S BRAKE DRUM, NEED TO REPLACE, REPLACED

Section 4 - Steering						
Component	P	F	NA	Component	P	F NA
4.1. Steering Control and Linkage	☒			4.4. Kingpin	☒	
4.2. Power Steering System (Hydraulic and Electric)	☒			4.5. Self-Steer and Controlled-Steer Axle	☒	
4.3. Steering Operation (Active Steer Axle)	☒					

NOTES:

Section 5 - Instruments and Auxiliary Equipment						
Component	P	F	NA	Component	P	F NA
5.1. Fire Extinguisher	☒			5.8. Heater & Windshield Defroster	☒	
5.2. Hazard Warning Kit	☒			5.9. Fuel-Burning Auxiliary Heater	☒	
5.3. Horn	☒			5.10. Chain/"Headache" Rack	☒	
5.5. Speedometer	☒			5.11. Auxiliary Controls and Devices		☒
5.6. Odometer	☒			5.12. Auxiliary Drive Controls		☒
5.7. Windshield Wiper/Washer	☒					

NOTES:

Section 6 - Lamps						
Component	P	F	NA	Component	P	F NA
6.1. Required Lamps	☒			6.4. Instrument Panel Lamps	☒	
6.2. Reflex Reflector	☒			6.5. Headlamp Aim	☒	
6.3. Retro-Reflective Marking	☒					

NOTES:

Section 7 - Electrical System						
Component	P	F	NA	Component	P	F NA
7.1. Wiring	☒			7.3. Trailer Cord (output to towed vehicle)	☒	
7.2. Battery	☒					

NOTES:

Section 8 - Body						
Component	P	F	NA	Component	P	F NA
8.1. Hood or Engine Enclosure	☒			8.12. Bumper	☒	
8.2. Tilt Cab		☒		8.13. Windshield	☒	
8.3. Air-Suspended Cab	☒			8.14. Side Windows	☒	
8.4. Cab and Passenger-Vehicle Body	☒			8.15. Rear Window		☒
8.5. Cargo Body		☒		8.16. Interior Sun Visor	☒	
8.6. Frame, Rails & Mounts	☒			8.17. Exterior Windshield Sun Visor	☒	
8.7. Utilized Body Elements	☒			8.18. Rear-View Mirror	☒	
8.8. Cab or Cargo Door	☒			8.19. Seat	☒	
8.9. Cargo Tank or Vessel		☒		8.20. Seat Belt/Occupant Restraint	☒	
8.10. Body, Device or Equipment Attached or Mounted to the	☒			8.21. Fender/Mud Flap	☒	

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 8 - Body						
Component	P	F	NA	Component	P	F NA
Vehicle						
8.11. Refrigeration/Heater Unit Fuel System (Reefer or Auxiliary Power Unit (APU))			✓	8.24. Aerodynamic Device & Attachment	✓	

NOTES:

REPAIRS COMPLETED R/S BUNK AIR BAG WORN OUT, REPLACED
 REPAIRS COMPLETED WINDSHIELD BROKEN NEED TO REPLACE, REPLACED
 REPAIRS COMPLETED B/S QUARTER FENDER NEED TO REPLACE, REPLACED

Section 9 - Tires and Wheels						
Component	P	F	NA	Component	P	F NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim (Applies to all wheel types)	✓	
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim		✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System		✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓	
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts and Studs)	✓	
9.6. Wheel Bearing	✓					

NOTES:

REPAIRS COMPLETED A2 R/S AND A3 R/S WHEEL SEAL LEAK, REPLACED

Section 10 - Couplers and Hitches						
Component	P	F	NA	Component	P	F NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.5. Roll-Coupling Hitch		✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.6. Automated Coupling Device		✓
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.7. Fifth Wheel Coupler	✓	
10.4. Ball Type Hitch			✓	10.8. Oscillating Fifth Wheel Coupler		✓

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8706801) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2026/05/29	C8385	20270	<i>DeLlenda</i>

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2026/05/29

Customer Signature



Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is "sold as is" no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture