

NH3-17

Alberta Government

CV8395133



80087300008395133

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Electric
Owner Name:	City of Lethbridge		
Address:	910 4 ave south		
City:	Lethbridge	Province:	AB
		Postal Code:	T1K 0P6
Telephone Number:	(403) 320-4030		
Vehicle Identification Number:	2S9LC546X71018186		
Make:	Southland	Model:	HighboyFlatdeck
Year:	2007	Unit Number:	07801
Odometer:	KM	Licence Plate Number:	V77841
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	K-Line Maintenance & Construction Limited	Facility Number:	16552
Inspection Technician Name:	Cody Michaelis	Technician Number:	B7160
Inspection Technician Signature:			
Inspection Date:	2025/10/08		

2025/10/30

NH3-

Handwritten text at the top right, possibly a name or date.

Faint, illegible text in the upper section of the page.

Large block of very faint, illegible text in the middle section of the page.

Large block of very faint, illegible text in the lower-middle section of the page.

Large block of very faint, illegible text at the bottom of the page.



COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle												Gross Vehicle Weight registered					
Trailer												kg					
Vehicle Information																	
VIN	2	S	9	L	C	5	4	6	X	7	1	0	1	8	1	8	6
Unit Number 07801			Year 2007			Make Southland			Model HighboyFlatdeck			Odometer					
Registered Owner's Name City of Lethbridge												Plate Number V77841					
Address 910 4 ave south									Postal Code T1K 0P6			Phone Number (403) 320-4030					

Drum Brakes: A-Full Inspection with Drum Removed

Disc Brakes:

		LEFT	FRONT	RIGHT		
78 psi	na psi	12.04 in	Drums/Rotors	12.04 in	na psi	80 psi
11/32 in	na in	0.16 in	Linings/Pads	0.17 in	na in	11/32 in
		na in	Push Rod Travel	na in		
72 psi	na psi	12.03 in	Drums/Rotors	12.04 in	na psi	79 psi
11/32 in	na in	0.15 in	Linings/Pads	0.17 in	na in	8/32 in
		na in	Push Rod Travel	na in		
17 psi	na psi	12.04 in	Drums/Rotors	12.04 in	na psi	80 psi
10/32 in	na in	0.16 in	Linings/Pads	0.18 in	na in	10/32 in
		na in	Push Rod Travel	na in		
psi	psi	in	Drums/Rotors	in	psi	psi
in	in	in	Linings/Pads	in	in	in
		in	Push Rod Travel	in		
psi	psi	in	Drums/Rotors	in	psi	psi
in	in	in	Linings/Pads	in	in	in
		in	Push Rod Travel	in		
psi	psi	in	Drums/Rotors	in	psi	psi
in	in	in	Linings/Pads	in	in	ir
		in	Push Rod Travel	in		

Park Brake Lining Left na in Right na in Trans na in

Wheel Torque Checked Inner na ft lbs Outer 140 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓

NOTES:

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension			✓
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle			✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly			✓
2.4. Spring & Spring Attachment			✓				

NOTES:

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System	✓		
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components	✓		
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components			✓
3H.8. Vacuum System			✓	3H.19. Brake Performance			✓
3H.9. Air-Boosted Trailer Brake System			✓				

NOTES:

break away has wires exposed and not working
all repairs complete

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage			✓	3A.16. S-Cam Drum Brake System			✓
3A.4. Air Tank			✓	3A.17. Brake Shoe Travel (Wedge Brakes)			✓
3A.8. Brake Valves & Controls			✓	3A.18. Disc Brake System Components			✓
3A.12. Parking Brake & Emergency Application			✓	3A.20. Anti-Lock Brake System (ABS)			✓
3A.13. Air System Components			✓	3A.22. Stability Control System (ESC) or (RSS)			✓
3A.14. Brake Chamber			✓	3A.23. Brake Performance			✓
3A.15. Drum Brake System Components			✓				

NOTES:

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle			✓
4.4. Kingpin			✓				

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery	✓						

NOTES:

breakaway battery dead
all repairs complete

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body	✓			8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements	✓			8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door	✓			8.23. Sliding Axle Assembly (Sliding Bogie)	✓		
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.25. Rear Impact Guard (RIG)			✓

NOTES:

right front removably side deck has missing upright
all repairs complete

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System			✓
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

one low psi
adjust wheel bearings
all repairs complete

Section 10 - Couplers and Hitches


Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)	✓			10.7. Fifth Wheel Coupler			✓
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch	✓			10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8395133) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2025/10/08	B7160	16552	

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2025/10/08

Customer Signature



Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is "sold as is" no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture