



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Electric
Owner Name:	city of lethbridge		
Address:	910 4 ave south		
City:	lethbridge	Province:	AB
		Postal Code:	T1J 0P6
Telephone Number:	(403) 320-4030		
Vehicle Identification Number:	5E3SK16N361000124		
Make:	wheeler reeler	Model:	slaback 60
Year:	2006	Unit Number:	06802
Odometer:	KM	Licence Plate Number:	5XN729
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
K-Line Maintenance & Construction Limited	16552
Inspection Technician Name:	Technician Number:
Cody Michaelis	B7160
Inspection Technician Signature:	
Inspection Date:	2025/04/03

2026/04/03



COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.


Type of Vehicle		Gross Vehicle Weight registered																																																																																							
Trailer		kg																																																																																							
Vehicle Information																																																																																									
VIN	5	E	3	S	K	1	6	N	3	6	1	0	0	0	1	2	4																																																																								
Unit Number	Year		Make		Model		Odometer																																																																																		
06802	2006		wheeler reeler		slaback 60																																																																																				
Registered Owner's Name														Plate Number																																																																											
city of lethbridge														5XN729																																																																											
Address										Postal Code		Phone Number																																																																													
910 4 ave south										T1J 0P6		(403) 320-4030																																																																													
Drum Brakes: A-Full Inspection with Drum Removed												Disc Brakes:																																																																													
<table border="1"><thead><tr><th colspan="2">LEFT</th><th colspan="2">FRONT</th><th colspan="2">RIGHT</th></tr></thead><tbody><tr><td>73 psi</td><td>na psi</td><td>12.03 in</td><td>Drums/Rotors</td><td>12.03 in</td><td>na psi</td><td>71 psi</td></tr><tr><td>13/32 in</td><td>na in</td><td>0.18 in</td><td>Linings/Pads</td><td>0.20 in</td><td>na in</td><td>12/32 in</td></tr><tr><td></td><td></td><td>na in</td><td>Push Rod Travel</td><td>na in</td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>												LEFT		FRONT		RIGHT		73 psi	na psi	12.03 in	Drums/Rotors	12.03 in	na psi	71 psi	13/32 in	na in	0.18 in	Linings/Pads	0.20 in	na in	12/32 in			na in	Push Rod Travel	na in																																																					
LEFT		FRONT		RIGHT																																																																																					
73 psi	na psi	12.03 in	Drums/Rotors	12.03 in	na psi	71 psi																																																																																			
13/32 in	na in	0.18 in	Linings/Pads	0.20 in	na in	12/32 in																																																																																			
		na in	Push Rod Travel	na in																																																																																					
Park Brake Lining Left na in Right na in Trans na in																																																																																									
Wheel Torque Checked ☒ Inner na ft lbs Outer 120 ft lbs																																																																																									

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED (Certificate #8395108)** the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection 2025/04/03	Technician Number B7160	Facility Number 16552	Signature 
Customer Acknowledgment			
I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.			Date (Year/Month/Day) 2025/04/03
			Customer Signature



Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is “sold as is” no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture