

N43-3



CV8395111



80087900008395111

CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Electric
Owner Name:	city of lethbridge		
Address:	910 4th ave south		
City:	lethbridge	Province:	AB
		Postal Code:	T1J 0P6
Telephone Number:	(403) 320-4030		
Vehicle Identification Number:	123WM282751T25134		
Make:	Sherman&Reilly	Model:	3 Wheel Turret
Year:	2005	Unit Number:	05802
Odometer:	KM	Licence Plate Number:	917333
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
K-Line Maintenance & Construction Limited	16552
Inspection Technician Name:	Technician Number:
Cody Michaelis	B7160
Inspection Technician Signature:	
Inspection Date:	2025/04/08

2026/04/30



COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle														Gross Vehicle Weight registered																																																																																																																		
Trailer														kg																																																																																																																		
Vehicle Information																																																																																																																																
VIN	1	2	3	W	M	2	8	2	7	5	1	T	2	5	1	3	4																																																																																																															
Unit Number 05802				Year 2005				Make Sherman&Reilly				Model 3 Wheel Turret				Odometer																																																																																																																
Registered Owner's Name city of lethbridge														Plate Number 917333																																																																																																																		
Address 910 4th ave south										Postal Code T1J 0P6				Phone Number (403) 320-4030																																																																																																																		
Drum Brakes: A-Full Inspection with Drum Removed Disc Brakes:																																																																																																																																
<table border="1"><thead><tr><th colspan="2">LEFT</th><th colspan="2">FRONT</th><th colspan="2">RIGHT</th></tr></thead><tbody><tr><td>93 psi</td><td>93 psi</td><td>12.25 in</td><td>Drums/Rotors</td><td>12.27 in</td><td>90 psi</td><td>90 psi</td></tr><tr><td>23 in</td><td>23 in</td><td>0.39 in</td><td>Linings/Pads</td><td>0.38 in</td><td>22 in</td><td>22 in</td></tr><tr><td></td><td></td><td>na in</td><td>Push Rod Travel</td><td>na in</td><td></td><td></td></tr><tr><td>93 psi</td><td>93 psi</td><td>12.27 in</td><td>Drums/Rotors</td><td>12.27 in</td><td>89 psi</td><td>90 psi</td></tr><tr><td>22 in</td><td>21 in</td><td>0.38 in</td><td>Linings/Pads</td><td>0.36 in</td><td>21 in</td><td>23 in</td></tr><tr><td></td><td></td><td>na in</td><td>Push Rod Travel</td><td>na in</td><td></td><td></td></tr><tr><td></td><td></td><td></td><td>Drums/Rotors</td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td>Linings/Pads</td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td>Push Rod Travel</td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td>Drums/Rotors</td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td>Linings/Pads</td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td>Push Rod Travel</td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td>Drums/Rotors</td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td>Linings/Pads</td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td>Push Rod Travel</td><td></td><td></td><td></td></tr></tbody></table>																		LEFT		FRONT		RIGHT		93 psi	93 psi	12.25 in	Drums/Rotors	12.27 in	90 psi	90 psi	23 in	23 in	0.39 in	Linings/Pads	0.38 in	22 in	22 in			na in	Push Rod Travel	na in			93 psi	93 psi	12.27 in	Drums/Rotors	12.27 in	89 psi	90 psi	22 in	21 in	0.38 in	Linings/Pads	0.36 in	21 in	23 in			na in	Push Rod Travel	na in						Drums/Rotors							Linings/Pads							Push Rod Travel							Drums/Rotors							Linings/Pads							Push Rod Travel							Drums/Rotors							Linings/Pads							Push Rod Travel			
LEFT		FRONT		RIGHT																																																																																																																												
93 psi	93 psi	12.25 in	Drums/Rotors	12.27 in	90 psi	90 psi																																																																																																																										
23 in	23 in	0.39 in	Linings/Pads	0.38 in	22 in	22 in																																																																																																																										
		na in	Push Rod Travel	na in																																																																																																																												
93 psi	93 psi	12.27 in	Drums/Rotors	12.27 in	89 psi	90 psi																																																																																																																										
22 in	21 in	0.38 in	Linings/Pads	0.36 in	21 in	23 in																																																																																																																										
		na in	Push Rod Travel	na in																																																																																																																												
			Drums/Rotors																																																																																																																													
			Linings/Pads																																																																																																																													
			Push Rod Travel																																																																																																																													
			Drums/Rotors																																																																																																																													
			Linings/Pads																																																																																																																													
			Push Rod Travel																																																																																																																													
			Drums/Rotors																																																																																																																													
			Linings/Pads																																																																																																																													
			Push Rod Travel																																																																																																																													
Park Brake Lining Left na in Right na in Trans na in Wheel Torque Checked <input checked="" type="checkbox"/> Inner na ft lbs Outer 500 ft lbs																																																																																																																																


**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

NOTES:

hitch mounting bolts loose
all repairs complete

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8395111) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection 2025/04/08	Technician Number B7160	Facility Number 16552	Signature 
Customer Acknowledgment I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.			Date (Year/Month/Day) 2025/04/08 Customer Signature



Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is “sold as is” no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture