



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	63500 kg	Brake Type:	Air
Owner Name:	DENNIS' DIRTWORX LTD		
Address:	PO BOX 1341		
City:	COALDALE	Province:	AB
		Postal Code:	T1M1N2
Telephone Number:	(403) 345-3539		
Vehicle Identification Number:	1XKWDU9X52R966806		
Make:	Kenworth	Model:	Construct
Year:	2002	Unit Number:	131
Odometer:	950325 KM	Licence Plate Number:	BZH3519
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Caps Diesel & Automotive Ltd	15737
Inspection Technician Name:	Technician Number:
Age Dejong	A8743
Inspection Technician Signature:	
Inspection Date:	2026/08/14

2027/08/14.

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle Truck		Gross Vehicle Weight registered 63500 kg															
Vehicle Information																	
VIN	1	X	K	W	D	U	9	X	5	2	R	9	6	6	8	0	6
Unit Number 131		Year 2002		Make Kenworth			Model Construct			Odometer 950,325							
Registered Owner's Name DENNIS' DIRTWORX LTD												Plate Number BZH3519					
Address PO BOX 1341										Postal Code T1M1N2		Phone Number (403) 345-3539					

Drum Brakes: A-Full Inspection with Drum Removed

Disc Brakes:

		<u>LEFT</u>		<u>FRONT</u>		<u>RIGHT</u>			
100 psi 12 mm		421.20 mm	Drums/Rotors	421.42 mm		90 psi			
		15.36 mm	Linings/Pads	15.76 mm		20 mm			
		23.24 mm	Push Rod Travel	23.43 mm					
80 psi 10 mm	70 psi 11 mm	422.46 mm	Drums/Rotors	421.24 mm		80 psi 10 mm	80 psi 10 mm		
		14.43 mm	Linings/Pads	13.99 mm					
		21.49 mm	Push Rod Travel	29.20 mm					
90 psi 9 mm	90 psi 11 mm	419.49 mm	Drums/Rotors	421.96 mm		100 psi 9 mm	90 psi 10 mm		
		21.51 mm	Linings/Pads	14.16 mm					
		27.96 mm	Push Rod Travel	29.32 mm					
			Drums/Rotors						
			Linings/Pads						
			Push Rod Travel						
			Drums/Rotors						
			Linings/Pads						
			Push Rod Travel						
			Drums/Rotors						
			Linings/Pads						
			Push Rod Travel						
Park Brake Lining Left <u>N/A</u> mm Right <u>N/A</u> mm Trans <u>N/A</u> mm Wheel Torque Checked ☒ Inner <u>N/A</u> ft lbs Outer <u>550</u> ft lbs									

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 8 - Body								
Component	P	F	NA	Component	P	F	NA	
8.8. Cab or Cargo Door	✓			8.19. Seat	✓			
8.9. Cargo Tank or Vessel			✓	8.20. Seat Belt/Occupant Restraint	✓			
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.21. Fender/Mud Flap	✓			
8.11. Refrigeration/Heater Unit Fuel System (Reefer or Auxiliary Power Unit (APU))			✓	8.24. Aerodynamic Device & Attachment				✓

NOTES:

PASSES AT TIME OF INSPECTION

Section 9 - Tires and Wheels								
Component	P	F	NA	Component	P	F	NA	
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim (Applies to all wheel types)	✓			
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim				✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System				✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System				✓
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts and Studs)	✓			
9.6. Wheel Bearing	✓							

NOTES:

MONITOR WHEEL TORQUES AND PRESSURES

RE-TORQUE ALL WHEELS AT 100km TO 550ft/lbs

ALL WHEELS BALANCED TO 100psi

AXLE #1 R/S WHEEL SEAL LEAKING DRUM & LININGS WET, REPAIRED

AXLE #2 BOTH WHEEL SEALS STARTING TO LEAK, DRUMS & LININGS DRY, REPAIRED

Section 10 - Couplers and Hitches								
Component	P	F	NA	Component	P	F	NA	
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.5. Roll-Coupling Hitch				✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.6. Automated Coupling Device				✓
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.7. Fifth Wheel Coupler	✓			
10.4. Ball Type Hitch			✓	10.8. Oscillating Fifth Wheel Coupler				✓

NOTES:

FIFTH WHEEL & BUSHINGS PAST SPEC, REPAIRED

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED (Certificate #8731064)** the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2026/08/14	A8743	15737	


Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2026/08/14

Customer Signature





Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is “sold as is” no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture