

Z05-5



CV8581451



80087300008581451

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	SUB TERRAIN EXCAVATING LTD		
Address:	BOX 95		
City:	IRON SPRINGS	Province:	AB
		Postal Code:	T0K1G0
Telephone Number:	(403) 795-4770		
Vehicle Identification Number:	2T9GAFEW25E008692		
Make:	Trojan	Model:	26'
Year:	2005	Unit Number:	
Odometer:	KM	Licence Plate Number:	
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
C.R. Mechanics Ltd.	15785
Inspection Technician Name:	Technician Number:
Cam Relter	B4953
Inspection Technician Signature:	
Inspection Date:	2026/05/25

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered											
Trailer										kg											
Vehicle Information																					
VIN	2	T	9	G	A	F	E	W	2	5	E	0	0	8	6	9	2				
Unit Number				Year 2005				Make Trojan				Model 26'				Odometer					
Registered Owner's Name SUB TERRAIN EXCAVATING LTD																Plate Number					
Address BOX 95												Postal Code T0K1G0				Phone Number (403) 795-4770					

Drum Brakes:	A-Full Inspection with Drum Removed	Disc Brakes:
--------------	-------------------------------------	--------------

		LEFT	FRONT	RIGHT		
100 psi	100 psi	420.68 mm	Drums/Rotors	420.33 mm	100 psi	100 psi
9 mm	10 mm	17 mm	Linings/Pads	16 mm	16 mm	14 mm
		45 mm	Push Rod Travel	49 mm		
100 psi	100 psi	421.08 mm	Drums/Rotors	420.7 mm	100 psi	100 psi
10 mm	7 mm	13 mm	Linings/Pads	14 mm	16 mm	16 mm
		47 mm	Push Rod Travel	50 mm		
100 psi	100 psi	420.19 mm	Drums/Rotors	420.20 mm	100 psi	100 psi
10 mm	9.5 mm	13 mm	Linings/Pads	14 mm	14.5 mm	11 mm
		50 mm	Push Rod Travel	48 mm		
100 psi	100 psi	420.48 mm	Drums/Rotors	420.68 mm	100 psi	100 psi
16 mm	16 mm	20 mm	Linings/Pads	19 mm	16 mm	8 mm
		50 mm	Push Rod Travel	50 mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		

Park Brake Lining	Left	NA	mm	Right	NA	mm	Trans	NA	mm
Wheel Torque Checked	☒	Inner	NA	ft lbs	Outer	500	ft lbs		

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓

NOTES:

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓		
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle			✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly			✓
2.4. Spring & Spring Attachment			✓				

NOTES:

4 AIR BAGS HAVE CORDS SHOWING/REPLACE ALL 4 BAGS
1SHOCK LEAKING/CUT OFF AND REPLACE SHOCK

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System			✓
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components			✓
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components			✓
3H.8. Vacuum System			✓	3H.19. Brake Performance			✓
3H.9. Air-Boosted Trailer Brake System			✓				

NOTES:

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System	✓		
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓
3A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components			✓
3A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)	✓		
3A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)			✓
3A.14. Brake Chamber	✓			3A.23. Brake Performance	✓		
3A.15. Drum Brake System Components	✓						

NOTES:

ABS LIGHT ON/MODULE NO GOOD REPLACE
AIR POT LEAKING/REPLACE BRAKE POT
ABS LIGHT ON DIM ALL THE TIME /WRONG LIGHT INSTALLED
REPLACE 2 CAGE BOLTS THAT WERE MISSING

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle			✓
4.4. Kingpin			✓				

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

NOTES:

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

4 CLEARANCE LIGHT WERE OUT/REPLACE ALL 4 LIGHTS WITH ONE PIGTAIL THAT WAS NO GOOD

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)			✓
7.2. Battery			✓				

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body	✓			8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Utilized Body Elements	✓			8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door			✓	8.23. Sliding Axle Assembly (Sliding Bogie)			✓
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.25. Rear Impact Guard (RIG)			✓

NOTES:

PIVOT PINS ON THE REAR OF THE TRAILER ARE WORN OUT/CUSTOMER TOOK TRAILER IN AND HAD HORIZON REPAIR THIS THEN BROUGHT BACK FOR US TO REINSPECT
REAR MUD FLAP MISSING/REPLACE MUDFLAP

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System			✓
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

REPLACED 5 TIRES THAT WERE NO GOOD

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)	✓			10.7. Fifth Wheel Coupler			✓



Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is "sold as is" no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture