



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION


Vehicle Type:		Trailer		Seating Capacity:		acity:			2-1-		
GVW:		kg		Brake Type:			Air				
Owner Name:		ASHTALE CONTRACTING LTD									
Address:	ASH	HTALE CONTRAC	CTING LTD	D, BOX 24	436, R	OCKY MO	DUNTAI	N			
City: ROCKY MOU		CKY MOUNTAIN	HOI Pro	Province: AB		Pos		Post	al Code:	T4T	1J6
Telephone	Num	ber: (403) 34	18-7004						M		
Vehicle Identification Number: 2PLB04037LB0			7LBC1	18839							
Make: Peerless					Model: B Trail Logger						
Year: 2020					Unit Number:			839 LEAD			
Odometer:		KM	Licence	ence Plate Number		: 5UA604			Province	e:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:	
Ashtale Contracting Ltd.	21323	
Inspection Technician Name	:	Technician Number:
Sheldon Ames		C9788
Inspection Technician Signa	ture:	Bar
Inspection Date:	2025/08/07	







CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:		Trailer		Seating Cap		city:		-	-		-		
GVW:		kg		Brake Type:			Air						
Owner Name: ASHTALE CONTRACTING LTD													
Address:	ВО	X 2436, ROCKY N	MOUN	NTAIN									
City:	City: ROCKY MOUNTAIN HOL		Province:	rovince: AB			Postal Code: T4T		1J6				
Telephone	Num	ber: (403) 34	8-70	04					To a				
Vehicle Identification Number: 2PLB02823LBC				3LBC18	18840								
Make: Peerless						Model: B Train Logger							
Year: 2020						Unit Number:							
Odometer:		KM	Lic	ence Plate Νι	umber:	r: 5UA605			Province	e:	AB		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:		Facility Number:			
Ashtale Contracting Ltd.	21323				
Inspection Technician Name):	Technician Number:			
Sheldon Ames		C9788			
Inspection Technician Signa	ture:				
Inspection Date: 2025/08/07					

