



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION


Vehicle Type:		Trailer		Seating Capa	city:			
GVW:		kg		Brake Type:	Air	Air		
Owner Name:		Drukade Transport LTD						
Address:	РО	PO Box 5633						
City:	Westlock			Province: AB		Postal Code:	T7P2P6	
Telephone	Num	ber:	(780) 307-47	30				
Vehicle Identification Number:			mber:	2DEGBSE35K2038492				
Make: Doepker					Model: GB21992L			
Year:	2019				Unit Number:	UNIT 13	UNIT 13	
Odometer: KM L		Lic	ence Plate Number:	5MH632	Province	e: AB		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:		
MechJager Mechanical Ltd.	15991		
Inspection Technician Name:	Technician Number:		
Ryan DeZaeyer	D2554		
Inspection Technician Signature:			
Inspection Date: 2025/01/06			







CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:		Trailer		Seating Capacity:				
GVW:		kg		Brake Type:		Air		
Owner Nan	ne:	Drukade Transport LTD						
Address:	PO Box 5633							
City:	Westlock			Province: AB		Р	ostal Code:	T7P2P6
Telephone	Num	ber:	(780) 307-47	30		Haut I	1-24/7	
Vehicle Identification Number:			2DEGBSA20K2038493					
Make:	Doepker				Mod	Model: GB21992R		
Year:	2019			THE RES	Unit Number:		UNIT 14	
Odometer:	Odometer: KM Lic		ence Plate Number:		6PJ842	Province	e: AB	

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:		
MechJager Mechanical Ltd.	15991		
Inspection Technician Name:	Technician Number:		
Ryan DeZaeyer	D2554		
Inspection Technician Signature:			
Inspection Date: 2025/01/06			

