



80087000008698952

CV8698952

216-31
Jeep

CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Site Resource Group Corp		
Address:	PO Box 210 STN Main		
City:	Cold Lake	Province:	AB
		Postal Code:	T9M 1P1
Telephone Number:	(780) 639-4844		
Vehicle Identification Number:	2A9JT6047BN125101		
Make:	Aspen	Model:	JT60-16/20
Year:	2011	Unit Number:	108-033
Odometer:	2778 KM	Licence Plate Number:	6UY288
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Site Resource Group GP Corporation	21951
Inspection Technician Name:	Technician Number:
Glen Glover	C4596
Inspection Technician Signature:	
Inspection Date:	2026/08/13



**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Site Resource Group Corp		
Address:	PO Box 210 STN Main		
City:	Cold Lake	Province:	AB
Postal Code:	T9M 1P1		
Telephone Number:	(780) 639-4844		
Vehicle Identification Number:	2A9TD4048BN125103		
Make:	Aspen	Model:	TD40-16/20
Year:	2011	Unit Number:	108-034
Odometer:	2687 KM	Licence Plate Number:	6UY287
Province:	AB		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Site Resource Group GP Corporation	21951
Inspection Technician Name:	Technician Number:
Jasen Reaume	C4695
Inspection Technician Signature:	
Inspection Date:	2026/08/10