R39-1





CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Ty	pe:	Truck	22105	Seating	Capacit	y:			
GVW:		31500 kg		Brake Type:		Air	Air		
Owner Name:		Bozco Enterprises Ltd.							
Address:	PO	PO BOX 1470							
City:	Pro	Provost		Province:	e: AB		Postal Code:	T0B-3S0	
Telephone	Num	ber: (780)	753-351	5					
Vehicle Ide	ntific	ation Number:		3ALPGND	R1DDBY	7933			
Make:	F	Freightliner			M	Model: Conventional			
Year:	2	2013			U	nit Number:	709	709	
Odometer:	12	238358 KM	Lice	nce Plate Nu	ımber:	L10404	Provinc	e: AB	

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number: 20377 Technician Number: B3248		
2337133 Alberta Ltd			
Inspection Technician Nam			
Darryl Boyko .			
Inspection Technician Sign	ature:	(ut)	
Inspection Date:	2025/02/18	911	