



**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Fluid Pro Oilfield Services Ltd.		
Address:	9701 99st		
City:	Clairmont	Province:	AB
		Postal Code:	T8X 5A8
Telephone Number:	(780) 533-3338		
Vehicle Identification Number:	1T9BL4036DS588671		
Make:	Tremcar	Model:	Super B
Year:	2013	Unit Number:	SB27A
Odometer:	KM	Licence Plate Number:	6WJ787
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Fluid Pro Oilfield Services Ltd.	20101
Inspection Technician Name:	Technician Number:
Taylor Alvarez	C8787
Inspection Technician Signature:	<i>Ta.</i>
Inspection Date:	2025/09/14



80087100008063158

CV8063158

M15-2

CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Fluid Pro Oilfield Services Ltd.		
Address:	9701 99st		
City:	Clairmont	Province:	AB
Postal Code:	T8X 5A8		
Telephone Number:	(780) 533-3338		
Vehicle Identification Number:	1T9BL322XDS588672		
Make:	Tremcar	Model:	Super B Pup
Year:	2013	Unit Number:	SB27B
Odometer:	KM	Licence Plate Number:	6KY387
Province:	AB		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Fluid Pro Oilfield Services Ltd.	Facility Number:	20101
Inspection Technician Name:	Taylor Alvarez	Technician Number:	C8787
Inspection Technician Signature:			
Inspection Date:	2025/09/14		