

H 44-8



CV7839710



80087400007839710

CERTIFICATE NUMBER

## Commercial Vehicle Inspection Certificate Traffic Safety Act

### PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Northwoods Oilfield Hauling Ltd.		
Address:	4819-90A AVE NW		
City:	EDMONTON	Province:	AB
		Postal Code:	T6B2Y3
Telephone Number:	(780) 518-8607		
Vehicle Identification Number:	2LDHG3027KF066850		
Make:	Lode King	Model:	HGF30-2P
Year:	2019	Unit Number:	273B
Odometer:	KM	Licence Plate Number:	6DA138
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

### PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Northwoods Oilfield Hauling Ltd	19206
Inspection Technician Name:	Technician Number:
Aaron Bergeron	C4589
Inspection Technician Signature:	
Inspection Date:	2024/09/06