



CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate**  
**Traffic Safety Act**

P39-2


**PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	EAST BUTTE TRANSPORT INC		
Address:	PO BOX 359		
City:	PICTURE BUTTE	Province:	AB
		Postal Code:	T0K1V0
Telephone Number:	(403) 635-0385		
Vehicle Identification Number:	1W1NCFGAXBB256383		
Make:	Wilson	Model:	PDWH-550
Year:	2011	Unit Number:	AT10B
Odometer:	KM	Licence Plate Number:	6HD463
		Province:	AB

**IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE**

**PART 2 - CERTIFICATION**

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
A.S.A.P Truck & Trailer Repairs Ltd.	13437
Inspection Technician Name:	Technician Number:
Fred Darroch	A7089
Inspection Technician Signature:	
Inspection Date:	2025/08/26