



CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	24400 kg	Brake Type:	Air
Owner Name:	GGA ALBERTA LTD		
Address:	12911 160 AVE NW		
City:	EDMONTON	Province:	AB
		Postal Code:	T6V1L5
Telephone Number:	(780) 974-6646		
Vehicle Identification Number:	1HTWNAZR0BJ420649		
Make:	International	Model:	7000 Series
Year:	2011	Unit Number:	
Odometer:	349964 KM	Licence Plate Number:	06R457
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
D-Tech Diesel Repair Ltd.	18312
Inspection Technician Name:	Technician Number:
Amrik Grewal	B8057
Inspection Technician Signature:	
Inspection Date:	2026/04/18

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle Truck	Gross Vehicle Weight registered 24400 kg																
Vehicle information																	
VIN	1	H	T	W	N	A	Z	R	0	B	J	4	2	0	6	4	9
Unit Number	Year		2011		Make		International		Model		7000 Series		Odometer		349,984		
Registered Owner's Name GCA ALEPRTA LTD														Plate Number 06R457			
Address 12911 160 AVE 11														Postal Code T6V1L5		Phone Number (780) 974-5646	

Drum Brakes:	A Full Inspection with Drum removed	Disc Brakes:
--------------	-------------------------------------	--------------

LEFT		FRONT		RIGHT	
100 psi 5 mm	419.88 mm 18 mm 28 mm	Duma/Rotors Lining/Pads Push Rod Travel	420.08 mm 16 mm 28 mm	100 psi 3 mm 100 psi 3 mm	5 psi 3 mm 7 psi 7 mm
100 psi 3 mm	419.89 mm 14 mm 32 mm	Duma/Rotors Lining/Pads Push Rod Travel	420.08 mm 13 mm 32 mm	100 psi 3 mm 100 psi 3 mm	5 psi 3 mm 7 psi 7 mm
100 psi 5 mm 6 mm	420.5 mm 11 mm 32 mm	Duma/Rotors Lining/Pads Push Rod Travel	419.15 mm 13 mm 32 mm	100 psi 3 mm 100 psi 3 mm	5 psi 3 mm 7 psi 7 mm
psi mm	mm mm mm	Duma/Rotors Lining/Pads Push Rod Travel	mm mm mm	psi mm psi mm	psi mm psi mm
psi mm	mm mm mm	Duma/Rotors Lining/Pads Push Rod Travel	mm mm mm	psi mm psi mm	psi mm psi mm
psi mm	mm mm mm	Duma/Rotors Lining/Pads Push Rod Travel	mm mm mm	psi mm psi mm	psi mm psi mm

Park Brake Lining Left 11 mm Right 13 mm Trans. NA mm
 Wheel Torque Checked ☒ Inner NA ft lbs Outer 500 ft lbs

VSSROI2018

P=PASS F=FAIL NA=Not Applicable

Page 1 of 4

COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

Section 3A - Air Brakes							
Component	P	F	NA	Component	P	F	NA
3A.11. Parking Brake & Emergency Application			✓				

NOTES:

Section 4 - Steering							
Component	P	F	NA	Component	P	F	NA
4.1 Steering Control Unit				4.4 Kingpin			
4.2 Power Steering System (Hydraulic and Electric)				4.5. Steer/Steer and Controlled Steer Axis			✓
4.3 Steering Operation (Active Steer Axis)			✓				

NOTES:

Section 5 - Instruments and Auxiliary Equipment					
Component	P	NA	Component	P	NA
5.1 Fire Extinguisher	✓		5.6 Heater & Washfield Defroster	✓	
5.2 Hazard Warning Kit	✓		5.9 Fuel Burning Auxiliary Heater	✓	
5.3 First Aid Kit	✓		5.10 Chain "Pothole" Plugs	✓	
5.4 Spare Wheel	✓		5.11 Tire Chains and Tire Devices	✓	
5.5 Spare Battery	✓		5.12 Auxiliary Drive Controls	✓	
5.6 Odometer	✓				
5.7 Washfield Wiper/Washer	✓				

NOTES:

Section 6 - Lamps						
	Component			Component		
	P	F	NA	P	F	NA
6.1. Required Lamps						
6.2. Reflex (Reflector)			✓	6.4. Instrument Panel Lamps		✓
6.3. Retro Reflective Marking			✓	6.5. Headlamp Aim		✓

NOTES:

Section 7 - Electrical System			
Component	P	F	NA
7.1 Wiring			
7.2 Battery			
7.3 Trailer Cord (output to towed vehicle)			

NOTES:

Component	Section 8 - Body			Component	P	NA
	P	F	NA			
8.1 Hood or Engine Enclosure				8.12 Bumper		
8.2 Tie Cab				8.13 Windshield	✓	✓
8.3 Air Suspended Cab			✓	8.14 Side Windows	✓	✓
8.4 Cab and Passenger Vehicle Body			✓	8.15 Rear Window	✓	✓
8.5 Cargo Body				8.16 Interior Sun Visor	✓	✓
8.6 Frame, Rails & Mounts				8.17 Exterior Windshield Sun Visor		
8.7 Cargo Body Mounting Components				8.18 Rear-View Mirror	✓	✓
8.8 Cab or Cargo Door				8.19	✓	✓
8.9 Cargo Tank or Vessel				8.20 Seat Belt/Occupant Restraint	✓	✓
8.10 Body, Device or Equipment Attached or Mounted to the				8.21 Fender/Mud Flap	✓	✓

VSSROI2018

P=PASS F=FAIL NA=Not Applicable

Page 3 of 4

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRUCK AND TRUCK-TRACTOR

	Section 8 - Body					
	Component			Component		
	P	F	N/A	P	F	N/A
Vehicle						
8.11 Refrigeration/Heater Unit Fuel System (Refrigerator or Auxiliary Power Unit (APU))				✓		✓

NOTES:

Section 9 - Tires and Wheels			
Component	F		NA
	P	NA	
9.1. Tire Tread Depth			
9.2. Tire Tread Condition			
9.3. Tire Sidewall & Manufacturer Markings			
9.4. Tire Inflation Pressure			
9.5. Tire Inflation Method			
9.6. Tire Inflation Record			
9.7. Wheel/Rim (Applies to all wheel types)			
9.8. Multi-Piece Wheel/Rim			
9.9. Spoke Wheel/Demonstrable Rim System			
9.10. Disc Wheel System			
9.11. Wheel Fasteners (Nuts, Bolts and Studs)			

NOTES:
2ND AXLE R/S HUBSEAL LEAK

Section 10: Couplers and Hitches			
Component	P	F	NA
10.1 Hitch Assembly, Structure & Anchoring Components			
10.2 Safety Chain, Hitch, or Coupler			
10.3 Breakdown Pin, Hitch, or Coupler Hitch			
10.4 Ball Hook Hitch			
10.5 Roll Coupling Hitch			
10.6 Automobile Coupling Device			
10.7 Ornamental Coupling Device			
10.8 Articulated Hitch Vehicle Coupler			
10.9 Airline Hitch Vehicle Coupler			

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8564068) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection _____

Technician Number

Facility Number

Customer Acknowledgment

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

100

Date (Year/Month) 2026/04/18
Customer Signa

VSSROI2018

P=PASS F=FAIL NA=Not Applicable

Page 4 of 4