ZH8-4





CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:		Trailer		Seatin	g Capac	ity:			
GVW:		kg		Brake Type:		Air	777		
Owner Nam	ie:	Mullen Trucking Corp.							
Address:	PO Box 87								
City:	Alde	ldersyde		Province:	AB		Postal Code:	T0L0A0	
Telephone	Num	ber: (403)	652-886	66					
Vehicle Identification Number:				2K9LB35378L052166					
Make:	kline				N	Model: trombone			
Year:	2	2008			ι	Unit Number: 48X003			
Odometer:		KM Licence Plat			umber:	mber: X29822		e: AB	

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	-	Facility Number:		
Mullen Trucking Corp.	10526			
Inspection Technician Name:		Technician Number:		
Jamie Hjalte	B6954			
Inspection Technician Signat	ure:			
Inspection Date:	2023/12/04			