L27-41





CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

| Vehicle Type: | | Trailer | | Seating Capacity: | | | | 2 | |
|--------------------------------|-----|--------------------|-----------------------|-------------------|------------|---------|------------|--------|--|
| GVW: | | kg | | Brake Type: | | Air | | | |
| Owner Nam | ne: | PIONEER TRI | ONEER TRUCK LINES LTD | | | | | | |
| Address: | 832 | 8321-1ST STREET NW | | | | | | | |
| City: | EDI | EDMONTON | | Province: | AB | | stal Code: | T6P1X2 | |
| Telephone | Num | ber: (780) | 467-888 | 30 | Walter and | | | | |
| Vehicle Identification Number: | | | | 2LDPF48249L048469 | | | | | |
| Make: Lode King | | | | Model: 48' Hiboy | | | | | |
| Year: | 1 | 2009 | | Unit Number: | | 223 | 2233 | | |
| Odometer: KM Li | | Lic | cence Plate Number: | | | Provinc | e: AB | | |

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

| Inspection Facility Name: | | Facility Number: | | |
|-----------------------------|------------|--------------------|--|--|
| Pioneer Truck Lines Ltd. | | 18279 | | |
| Inspection Technician Name |): | Technician Number: | | |
| Tucker Mullenix | 0.25 | C5848 | | |
| Inspection Technician Signa | ature: | La Market | | |
| Inspection Date: | 2025/04/10 | 7,00 | | |