



00001300000302010

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Typ	e:	Trailer	6	- 100 - 100	Seating C	apacit	y:					and the second
GVW:		kg	10	42.	Brake Ty	pe:		Air				
Owner Nam	ie:	MUDDA	ASAR SU		V						81,81	
Address:	P.0	P.O BOX 6002 EDSON LAB										
City:	EDN	EDMONTON			Province: AB				Post	al Code:	T7E	1T6
Telephone	Num	ber:	(000) 00	0-00	00							
Vehicle Ide	ntific	ation Nu	mber:		2E9L2DE21k	(30032	75	1				
Make:	5	cona	2			M	odel:	Tromb	one			
Year:	1	1989		U		Unit Number:		TL200				
Odometer: KM		Lic	Licence Plate Number:		4EK627		Province	e:	AB			

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:			
Fast Tire & Repair Service Ltd.	21106			
Inspection Technician Name:	At the	Technician Number:		
Anit Kumar		B1920		
Inspection Technician Signatur	e. ·	160		
Inspection Date:	2025/05/31			

COMMERCIAL VENICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

NOTES:

Certification			
The Vehicle for which this Record accordance with the Vehicle Inspec	of Inspection is issued has PASSED ction Regulation, Alberta Regulation	(Certificate #8362648) the inspection 211/2006 and the applicable Inspection	ion and I certify it has been inspected in named.
Date of Inspection 2025/05/31	Technician Number B1920	Facility Number 21106	Signature
Customer Acknowledgment			
the initial inspection and only the	n identifies defection and repairs are noted items noted on the ROI are re	nspection Facility within 10 days of	Date (Year/Month/Day) 2025/05/31
must be conducted.	ection within 10 days of the initial da	te of inspection, a new inspection	Customer Signature