



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION

X17-1

Vehicle Type:	Truck	Seating Capacity:	
GVW:	45600 kg	Brake Type:	Air
Owner Name:	UNITY AND HEALING REUNIFICATION LTD		
Address:	PO BOX 235		
City:	ATIKAMEG	Province:	AB
		Postal Code:	TOG0C0
Telephone Number:	(780) 523-0772		
Vehicle Identification Number:	1XKZDP0X4KJ950820		
Make:	Kenworth	Model:	Construct
Year:	2019	Unit Number:	2401503
Odometer:	583004 KM	Licence Plate Number:	0AY591
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
T. Yardley Contracting Ltd.	20929
Inspection Technician Name:	Technician Number:
Brett Callio	C6049
Inspection Technician Signature:	
Inspection Date:	2025/04/24