211-9





CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

GVW:	kg						
	I Ng	Brake	Type:	Air			
Owner Name: PIDHERNEYS INC		YS INC					
Address:	BOX 940						
City:	ROCKY MOUNT	AIN HOL Province:	AB	Po	stal Code:	T4T 1A7	
Telephone N	lumber: (403	3) 845-3072					
Vehicle Ident	tification Numbe	r: 2C9SBU3	2C9SBU3W8HM183103				
Make:	Cross County			Model: Tridem sidedump			
Year:	2017			nit Number:	3873		
Odometer:	409831 KM	409831 KM Licence Plate Numbe		5VH724	Province	: AB	

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:	
Pidherney's Inc.	11319	
Inspection Technician Name:	Technician Number:	
Kevin Hummel	D3141	
Inspection Technician Signatu	ire:	Mar les
Inspection Date:	2025/03/26	1