K12-2





#### CERTIFICATE NUMBER

### Commercial Vehicle Inspection Certificate Traffic Safety Act

# PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:		Truck		Seating Capacity:						
GVW:		63500 kg		Brake Type:			Air			
Owner Name:		TITAN SPECIALIZED HAULING LTD								
Address:	PO	BOX 7949 STN	NIAM I							
City:	ED:	EDSON		Province:	ce: AB			Postal Code: T7E1W2		
Telephone	Num	ber: (780)	723-66	43			, , , , , , , , , , , , , , , , , , , ,			
Vehicle Identification Number:				1NKCX4TX87R933447						
Make: Kenworth				Model: Construct						
Year:	2007				Unit Number: 361					
Odometer: 506631 KM Li		Lic	сепсе Plate Number:		A92795		Province	: AB		

## IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

### PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:		Facility Number:			
Dash Mechanical Edson Ltd	l.	17171			
Inspection Technician Nam	e:	Technician Number:			
Trevor Simmons	B9754				
Inspection Technician Sign	ature:				
Inspection Date:	2025/07/21				