Pia-9



Inspection Facility Name:



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:		Trailer		Seatin	Seating Capacity:				
GVW:		kg		Brake	Brake Type:		Air		
Owner Nan	ne:	1787766	1787766 ALBERTA LTD						
Address:	PO	PO BOX 383							
City:	DAY	YSLAND Pro		Province:	AB		ostal Code:	T0B1A0	
Telephone	Num	ber: (7	'80) 679-78	315					
Vehicle Ide	ntific	ation Num	ber:	2C9HSM3	3S5GM18	3713			
Make:	Meridian				IV	Model: Tender 1260			
Year:	2015				L	Unit Number:		754	
Odometer: 0 KM Lic		cence Plate Number:		5RV154	Provinc	e: AB			

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

Facility Number

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

moposition and and		radiity radiiber.		
Hahn's Mechanical Ltd.		20255		
Inspection Technician Nam	Technician Number:			
Kevin Hahn		C7939		
Inspection Technician Sign	ature:	I W MI		
Inspection Date:	2024/10/23			

Der The State In

HEEMILA ETAMPITARO

- Commercial deflicies (Con Certificate)

BLOWNS CAN RELEVO TO CHERVE THAT

		经证据的			
The second control of	7.7	एक्ट्रिक्ट्रिक विकास	lsy8	Telien?	Lay Fatablev
flydd diffelyd o chweru diffel fae eilydd glaffer a'r Llfach	tuu oo waxaa ee aa o Lab	· · · · · · · · · · · · · · · · · · ·		Old	
in the second second in the second				ZIZIBIA BUUU	ignst 1990
and the second problem of the region of the	y maga aryang kang taun ay ipi Jahas Ang kang aryang kang taun	menter et sist for de dispet son attende in de siste en de sis Siste en de siste en de sis		BOX 383	Ascress Pu
Postal Code: 1081A0	1	<u> </u>	1829157.13	CWARE	A STATE OF THE STA
page transpage. The antipolitical administration of a galaxy traper parties.	y may no tipoten a la l	The second secon		1. 0 (2.631) - m ad	muli processoral
and the second s		STREET OF	Heos	redunit noile	office bid on all
250	ร์ จะยังสรี	deficie	The second section of the second	80.15.15.	194911
587	្រ (៣	ar neu l'		ZV)	13-6Y
and takes to			ورد مناجعت الما		Dissipation Inc.
250 250 250 250 250 250 250 250	To veit as T	John 16	Heos	200 (1001) Ded 1001) Constant 10010 Constant 10010 (1001)	

HOUSE TEAS

a centry me vehicle oe arce em color tinos paco em colorador arba establishmo under ce tino no Sales, Arbare Communida Velado - เกิดเลือง Arbare Communida Velado

Facility Remissor:			inspection Fediaty Manor 🤍
88398			Table a be sonation Ltd.
Tachnician Number:		in the second se	unsif បន់ស្រីក្រសួង។ កក្សាននេះសា
02.750	, and the second se	A CONTRACTOR OF THE STATE OF TH	Fig. 3221 - 17 w 12 with the second s
The second secon	America Delicities - Victoria in the Control of the Control	gyana (mitro or or mighter class) such as the control of the	inspaction Technician Signatura.
makes a constraint efficiency constraint, characteristic tiple and effect broadchard from the constraint of the	and the second s	2010	esed not became