



CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Truck	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Colas Western Canada Inc.		
Address:	250 Carleton Drive		
City:	St. Albert	Province:	AB
Postal Code:	T8N6W2		
Telephone Number:	(780) 449-7507		
Vehicle Identification Number:	1NPWLB0X8D738078		
Make:	Peterbilt	Model:	Conventional
Year:	2008	Unit Number:	120570
Odometer:	818495 KM	Licence Plate Number:	CNX1940
Province:	AB		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Two Engines HD Repair Ltd.	16768
Inspection Technician Name:	Technician Number:
Michael Hudson	B3369
Inspection Technician Signature:	
Inspection Date:	2025/06/12