



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:		Trailer		Seating Capacity		/: - \			- 1	- 1	
GVW:		kg		Brake Type:			Air				
Owner Name:		Site Resource Group GP Corporation									
Address:	РО	PO Box 210									
City:	Cold	d Lake		Province:	AB			Posta	al Code:	Code: T9M 1P2	
Telephone Number: (780) 400-7483											
Vehicle Identification Number:				2D9EB53C191004009							
Make: Deloupe					Мо	del: EB53					
Year:	2	009		Unit Number:				106-039			
Odometer: 5		5080 KM	Lic	Licence Plate Number		:	6VL857		Province	e:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:		Facility Number:				
Site Resource Group GP C	orporation	21772				
Inspection Technician Nam	ne:	Technician Number:				
Tom Sacco		A3371				
Inspection Technician Sign	ature:	I on				
Inspection Date:	2025/07/09					