



**CERTIFICATE NUMBER**

## Commercial Vehicle Inspection Certificate Traffic Safety Act

### PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	63500 kg	Brake Type:	Air
Owner Name:	freight north carriers inc		
Address:	18 wrangle pl se		
City:	calgary	Province:	AB
		Postal Code:	T1X0L7
Telephone Number:	(403) 266-4131		
Vehicle Identification Number:	3ALXFBCG1JDJW2279		
Make:	Freightliner	Model:	Conventional
Year:	2018	Unit Number:	4-193
Odometer:	763871 KM	Licence Plate Number:	0AX543
		Province:	AB

**IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE**

### PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Docktor Freight Solutions Corp.	16372
Inspection Technician Name:	Technician Number:
Richard Arandela	C7322
Inspection Technician Signature:	
Inspection Date:	2024/10/30