



Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	63500 kg	Brake Type:	Air
Owner Name:	freight north carriers inc		
Address:	18 wrangle pl se		
City:	calgary	Province:	AB
Postal Code:	T1X0L7		
Telephone Number:	(403) 266-4131		
Vehicle Identification Number:	3AKJGLDV8FSGE5618		
Make:	Freightliner	Model:	Cascadia
Year:	2015	Unit Number:	4-307
Odometer:	1078832 KM	Licence Plate Number:	OCA155
Province:	AB		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Docktor Freight Solutions Corp.	16372
Inspection Technician Name:	Technician Number:
Richard Arandela	C7322
Inspection Technician Signature:	
Inspection Date:	2025/01/28