



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	KD GROUP LTD		
Address:	2113 89B ST SW		
City:	EDMONTON	Province:	AB
		Postal Code:	T6X0R9
Telephone Number:	(780) 271-2022		
Vehicle Identification Number:	2D9ED2927W1012084		
Make:	Loadline	Model:	n/a
Year:	1998	Unit Number:	
Odometer:	KM	Licence Plate Number:	6GD244
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
North Truck and Trailer Repair Ltd.	19938
Inspection Technician Name:	Technician Number:
Daljeet Dhillon	D1976
Inspection Technician Signature:	
Inspection Date:	2025/08/14