



80087200008083580

CERTIFICATE NUMBER

F39-2.

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE

				IDENTIN IO	71101	•				
Vehicle Type:		Truck		Seating Capacity:		ty:		Alexander		
GVW:		24300 kg		Brake Type:		Air				
Owner Name:		Allstar Construction Ltd								
Address:	111	130-199st								
City:	Edr	Edmonton		Province:	vince: AB		Postal Code:	T5S-2C6		
Telephone	Num	ber: (780)	452-633	0						
Vehicle Identification Number:			1NKDLU0X22R965033							
Make: Kenworth				Model: Constr		ıct				
Year:	: 2002				Unit Number:		BT03			
Odometer: 90112 KM		90112 KM	Lice	Licence Plate Number:		CVB1475	Provinc	ce: AB		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:			Facility Number:
Allstar Construction Ltd.		16821	
Inspection Technician Name:	/	/	Technician Number:
David Froehlich			A6081
Inspection Technician Signature:			
Inspection Date:	2024/12/23		