

A15-15



CV8265829



80087300008265829

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	63500 kg	Brake Type:	Air
Owner Name:	freight north carriers inc		
Address:	18 wrangle pl se		
City:	calgary	Province:	AB
		Postal Code:	T1X0L7
Telephone Number:	(403) 266-4131		
Vehicle Identification Number:	1XKDD49X8JJ990845		
Make:	Kenworth	Model:	Construct
Year:	2018	Unit Number:	4-314
Odometer:	962838 KM	Licence Plate Number:	0EA265
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Docktor Freight Solutions Corp.	16372
Inspection Technician Name:	Technician Number:
Richard Arandela	C7322
Inspection Technician Signature:	
Inspection Date:	2025/05/29