J13-1





CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

Y01-1

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Odometer:	2	14829 KM	Lic	icence Plate Number		A333	A33338		e: AB		
Year:	2	2003			T	Unit Number:		T700	T700		
Make:	K	Cenworth			P	/lodel:	Construc	:t			
Vehicle Identification Number:				1XKDDB0	1XKDDB0X03R969316						
Telephone	Num	ber: (780)	689-21	21							
City:	BOYLE			Province:	Province: AB			Postal Code: T0A 0M0			
Address:	РО	PO BOX 99									
Owner Name:		ALLNITE TRUCKING LTD									
GVW:		kg		Brake Type:			Air				
Vehicle Type:		Truck		Seating Capacity:		ity:					

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:		Facility Number:			
BRV Truck & Trailer Repairs	s Ltd.	20375			
Inspection Technician Nam	e:	Technician Number:			
Balwinder Natt		C8422			
Inspection Technician Sign	ature:	1 Vouler			
Inspection Date:	2025/10/10				