



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:		Trailer		Seating Capacity:		ty:			
GVW:		kg		Brake	Туре:	Air	Air		
Owner Name:		CANADIAN LYNDEN TRANSPORT LTD							
Address:	400	00 ACHESON 20-53016 HWY 60							
City:	SPF	SPRUCE GROVE		ovince:	AB		Postal Code:	T7X3G7	
Telephone	Num	ber: (780) 9	963-0944						
Vehicle Ide	ntific	ation Number:		2M51216	1X911198	73			
Make:	N	Manac			IV	Model: Tandem			
Year:	2	2009			Unit Number:		553225	553225	
Odometer:	1 KM Licence			e Plate N	Plate Number: W96527		Provinc	e: AB	

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:		Facility Number:		
Gateway Trailer Repairs LTo	1.	18189		
Inspection Technician Name	e:	Technician Number:		
Elizaldy Recla		C9168		
Inspection Technician Signa	ature:			
Inspection Date:	2025/02/11			