117-52





CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:		Truck			Seating Capacity:							
GVW:		63500 kg			Brake Type:			Air				
Owner Name:		CHALLAND PIPELINE LTD										
Address:	ВО	3OX 1807										
City:	RO	OCKY MOUNTIAN HOL Prov			/ince:	AB	Pos			al Code: T4T1B4		1B4
Telephone Number: (403) 845-2469												
Vehicle Identification Number:				11	1NKDX4TXXDR962321							
Make: Kenworth					Model:			el: Constru	Construct			
Year:	2	2013		Unit Number			Number:		1321			
Odometer:	8	818275 KM Licen			Plate Nu	mber	: к	K37611		Province	e:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:		Facility Number:			
Challand Pipeline Ltd.		12183			
Inspection Technician Name:			Technician Number:		
John VandenBrink	200.00	***************************************	A7567		
Inspection Technician Signature:		A	of Walls		
Inspection Date:	2025/09/12				