



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:		Truck			Seating Capacity:			:					
GVW:		23300 kg			Brake Type:				Air				
Owner Nam	ie:	CHALLAND PIPELINE LTD											
Address:	во	BOX 1807											
City:	RO	OCKY MOUNTIAN HOL Pro			ince:	nce: AB				Postal Code:		T4T	1B4
Telephone Number: (403) 845-2469													
Vehicle Identification Number:				2NP3LJ9X2FM259815									
Make: Peterbilt					Model:			del:	Conventional				
Year: 2015								Unit Number:			1543		
Odometer:		158560 KM	Lic	ence	Plate Number		:	H218	1858		Provinc	e:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:				
Challand Pipeline Ltd.	12183				
Inspection Technician Name:		Technician Number:			
John VandenBrink	A7567				
Inspection Technician Signate	ure:	Goldonlo			
Inspection Date:	2025/05/22				