417-82





CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

| Vehicle Type: | | Trailer | | Seating Capacity: | | ity: | | 7 | | |
|--------------------------------|--------|---------------|-----------|-------------------|------------------|----------|--------------|----------|-------|--|
| GVW: | | kg | | Brake Type: | | | Air | | | |
| Owner Nan | ne: | CHALLAND PIP | ELINE | LTD | | | | A . | | |
| Address: | ВО | BOX 1807 | | | | | | | | |
| City: | RO | CKY MOUNTIAN | Province: | AB | | I | Postal Code: | T4T1B4 | | |
| Telephone | Num | ber: (403) 84 | 5-246 | 9 | | | | The sale | | |
| Vehicle Identification Number: | | | | 2K9TD1111FL072087 | | | | | | |
| Make: | Gerrys | | | 1 | Model: Booste | | ooster | | | |
| Year: | 12 | 2015 | | | U | Jnit Num | ber: | 252 | | |
| Odometer: | | KM Licence | | ence Plate N | ce Plate Number: | | 4VK152 | | e: AB | |

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

| Inspection Facility Name: | Facility Number: | | | |
|-----------------------------|------------------|--------------------|--|--|
| Challand Pipeline Ltd. | 12183 | | | |
| Inspection Technician Name |): | Technician Number: | | |
| John VandenBrink | A7567 | | | |
| Inspection Technician Signa | ture: | Goldand Bo | | |
| Inspection Date: | 2024/11/08 | | | |