



Commercial Vehicle Inspection Certificate
Traffic Safety Act

P309


PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	SANDYS OILFIELD HAULING LTD		
Address:	2306B 8 ST		
City:	NISKU	Province:	AB
		Postal Code:	T9E7Z2
Telephone Number:	(780) 955-8600		
Vehicle Identification Number:	2PLH02629WBH89010		
Make:	Peerless	Model:	JP-30-8A
Year:	1998	Unit Number:	SH63
Odometer:	KM	Licence Plate Number:	N08469
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Sandy's Oilfield Hauling Ltd.	11496
Inspection Technician Name:	Technician Number:
Michael Taylor	A2992
Inspection Technician Signature:	
Inspection Date:	2025/10/08