



Commercial Vehicle Inspection Certificate Traffic Safety Act


PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Site Resource Group GP Corporation		
Address:	PO Box 210		
City:	Cold Lake	Province:	AB
Postal Code:	T9M 1P2		
Telephone Number:	(780) 400-7483		
Vehicle Identification Number:	2DEDDFZ39V1010543		
Make:	Doepker	Model:	Tridem Mach
Year:	1997	Unit Number:	106-034
Odometer:	37750 KM	Licence Plate Number:	6VL858
Province:	AB		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Site Resource Group GP Corporation	21772
Inspection Technician Name:	Technician Number:
Tom Sacco	A3371
Inspection Technician Signature:	
Inspection Date:	2025/10/10