



#### **CERTIFICATE NUMBER**

# Commercial Vehicle Inspection Certificate Traffic Safety Act

## PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:		Truck		Seating Capacity:		ity:			
GVW:		63500 kg		Brake	Type:	Air	Air		
Owner Name:		539169 ALBERTA LTD O/A MFP RESOURCES							
Address:	592	0 76 AVE NW							
City:	EDMONTON			Province: AB			Postal Code:	T6B 0A6	
Telephone	Num	ber: (780)	465-966	8					
Vehicle Identification Number:				1XPCDP9X2KD606856					
Make:	Peterbilt			l n	Model: Conventional				
Year:	2	2019			I	Unit Number: 53		533	
Odometer: 1036129 KM		Lice	Licence Plate Number:		A73923	Province	e: AB		

### IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

### **PART 2 - CERTIFICATION**

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:		Facility Number:		
Heavy Hauler Service & Re	11412			
Inspection Technician Nam	Technician Number:			
Douglas Krupa	A2607			
Inspection Technician Sign	ature:	1 Win		
Inspection Date:	2025/08/15	- Car		