

036-2



CV8515641



80087000008515641

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	63500 kg	Brake Type:	Air
Owner Name:	539169 ALBERTA LTD O/A MFP RESOURCES CORP		
Address:	5920 760 AVE NW		
City:	EDMONTON	Province:	AB
		Postal Code:	T6B 0A6
Telephone Number:	(780) 465-9868		
Vehicle Identification Number:	4V4NC9EH9JN890670		
Make:	Volvo	Model:	VN
Year:	2018	Unit Number:	537
Odometer:	658665 KM	Licence Plate Number:	CTD1897
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Heavy Hauler Service & Repair Ltd.	11412
Inspection Technician Name:	Technician Number:
Douglas Krupa	A2607
Inspection Technician Signature:	
Inspection Date:	2025/05/13