



Commercial Vehicle Inspection Certificate
Traffic Safety Act

536-1

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	63500 kg	Brake Type:	Air
Owner Name:	Racuda logistics inc.		
Address:	209 AUGUSTA BLVD E		
City:	WARMAN	Province:	SK
		Postal Code:	S0K4S1
Telephone Number:	(000) 000-0000		
Vehicle Identification Number:	1XKZD40X1HJ988822		
Make:	Kenworth	Model:	Construct
Year:	2017	Unit Number:	920R
Odometer:	812804 KM	Licence Plate Number:	178MAH
		Province:	SK

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Nexar Equipment Ltd.	20845
Inspection Technician Name:	Technician Number:
Joseph Hill	D2361
Inspection Technician Signature:	<i>Joseph Hill</i>
Inspection Date:	2025/10/15