



CV8225105



80087700008225105

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Truck	Seating Capacity:	
GVW:	63500 kg	Brake Type:	Air
Owner Name:	2XL TRANSPORT LTD		
Address:	507 EAGLESON WYND NW		
City:	EDMONTON	Province:	AB
		Postal Code:	T6M0Y5
Telephone Number:	(587) 988-5191		
Vehicle Identification Number:	1XKWD40X5JJ992073		
Make:	Kenworth	Model:	Construct
Year:	2018	Unit Number:	04
Odometer:	848627 KM	Licence Plate Number:	A14459
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Allspec Diesel Solutions Inc.	19376
Inspection Technician Name:	Technician Number:
Harpreet Tatla	C8249
Inspection Technician Signature:	
Inspection Date:	2025/01/15

Component		P	F	NA
Section 3A - Air Brakes				
NOTES:				
3A.11. Parking Brake & Emergency Application				
REPLACED 1ST DRIVE AXLE BOTH SIDE S-CAM AND S-CAM TUBES AND BUSHINGS AND REPLACED 1ST DRIVE AXLE LEFT BRAKEPOT AND ADJUST ALL BRAKES				
Section 4 - Steering				
NOTES:				
4.1. Steering Control and Lamps 4.2. Power Steering System (Hydraulic and Electric) 4.3. Steering Operation (Drive Shaft, Steer Axle)				
Component				
P	F	NA		
Section 5 - Instruments and Auxiliary Equipment				
NOTES:				
5.1. Engine Indicator 5.2. Hazard Warning Light 5.3. Horn 5.5. Speedometer 5.6. Odometer 5.7. Windshield Wiper/Washer 5.8. Auxiliary Drive Controls 5.9. Fuel/Throttle/Air/Fuel 5.10. Fuel/Throttle/Air/Fuel 5.11. Auxiliary Controls and Buttons				
Component				
P	F	NA		
Section 6 - Lamps				
NOTES:				
6.1. Rear/Land Lamp 6.2. Right Indicator 6.3. Rear/Headlight Lamp 6.4. Headlight Lamp 6.5. Headlight Arm				
Component				
P	F	NA		
Section 7 - Electrical System				
NOTES:				
7.1. Battery 7.2. Wiring				
Component				
P	F	NA		
Section 8 - Body				
NOTES:				
8.1. Hood or Engine Enclosure 8.2. Tire Cab 8.3. Cab and Engine Enclosure 8.4. Cab and Passenger/Operator Body 8.5. Cab Body 8.6. Frame, Bolt & Mount 8.7. Underbody Brackets 8.8. Cab or Cargo Door 8.9. Cargo Tank or Vessel 9.10. Body, Chassis or Equipment Attached or Mounted to Body 9.11. Fuel/Water Tank 9.12. Windshield 9.13. Windshield 9.14. Side Windows 9.15. Rear Window 9.16. Rear Window 9.17. Fuel/Water Tank 9.18. Fuel/Water Tank 9.19. Fuel/Water Tank 9.20. Fuel/Water Tank 9.21. Fuel/Water Tank				
Component				
P	F	NA		

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRUCK AND TRUCK-TRACTOR[illegible]COMMERCIAL VEHICLE RECORD OF INSPECTION
TRUCK AND TRUCK-TRACTOR